



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2502282

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/04/2025
Reference CD/CTI24110433/Ama3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 5579R
Insured Veh. SLE 9940J
Claim No. SNM24D205888
Policy No. DMCHSNW00001022400
Accident Date 20/10/2024
Inspection Date 12/11/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24110433/Ama3q2(N)	
			Date: 14/04/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 9940J	Veh. Inspected	SLF 5579R
	Policy No.	DMCHSNW00001022400	Coverage (\$)	0.00
	Claim No.	SNM24D205888	Excess (\$)	0.00
	Assign From		Assign Date	12/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	KIA FORTE K3	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KNAFZ411MH5637412	Colour	BLACK
	Odometer	216145 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/10/2024	Inspection Date	12/11/2024
	Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5579R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	668.00	668.00
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	43.00	-
1	FRONT BUMPER GRILLE CHROME	NOT NECESSARY	276.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	79.00	-
1	FRONT BUMPER FOGLAMP LH	CRACKED	268.00	268.00
1	FRONT BUMPER FOGLAMP COVER GARNISH LH	NOT NECESSARY	23.00	-
2	FRONT BUMPER SENSOR LH @\$195.00	NOT NECESSARY	390.00	-
2	FRONT BUMPER SIDE RETAINER @\$17.00	NOT NECESSARY	34.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	421.00	-
1	FRONT BUMPER SPONGE	CRACKED	123.00	123.00
1	FRONT FENDER INNER COWLING LH	NOT NECESSARY	109.00	-
2	HEAD LAMP (HID) @\$1870.00	N/S CRACKED	3,740.00	1,870.00
2	HEAD LAMP LOWER BRACKET @\$45.00	NOT NECESSARY	90.00	-
1	BONNET	NOT NECESSARY	877.00	-
1	BONNET LOCK	NOT NECESSARY	65.00	-
1	BONNET STOPPER	NOT NECESSARY	21.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	776.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	53.00	-
1	FRONT SUPPORT PANEL LOWER GARNISH	NOT NECESSARY	110.00	-
2	FRONT AIRCON CONDENSER SIDE GARNISH @\$21.00	NOT NECESSARY	42.00	-
	LESS 10% DISCOUNT		-820.80	-292.90
			7,387.20	2,636.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	BONNET SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET CENTER GRILLE CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	30.00	-

Report Ref No. CD/CTI24110433/Ama3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT AIRCON CONDENSER SIDE GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	COOLANT (SN)	NOT NECESSARY	60.00	-
			540.00	30.00
	LABOUR			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,200.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	200.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST .	NOT NECESSARY	80.00	-
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING.		80.00	50.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			2,720.00	550.00
GRAND TOTAL			10,647.20	3,216.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CD/CT124110433/Ama3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R



PHOTOGRAPHS FOR VEHICLE NO. : SLF 5579R

