

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110438/KUA3Q2**Date:** 05/12/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220066091
Claimant Vehicle No :	SKU5008E	Insured Vehicle No :	GBK4168S
Date of Loss:	20/11/2024	Nature of Claim:	TP
		Claim No:	0762417005SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU5008E	Engine No:	CAYAX0111
Make & Model:	VOLKSWAGEN TOURAN, 1.6 TDI (A)	Chassis No:	WVGZZZ1TZFW054920
Reg. Date:	31/07/2015 (Man. Year: 2015)	Odometer:	80419 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,108.70	6,470.70	1,638.00	20.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,790.00	430.00	19.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,328.70	8,260.70	2,068.00	20.02
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	10,328.70	6,000.00	4,328.70	41.91
+ GST 9.00/9.00% (S\$)	929.58	540.00	389.58	41.91
Nett Amount (S\$)	11,258.28	6,540.00	4,718.28	41.91
+ Car Rental (6.0 x S\$90.00/day + 9.00% GST) (S\$)		588.60		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,130.78		

INSPECTION

Date of Assignment:	26/11/2024	
Date Inspected:	26/11/2024	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,100.00 FL	*1,100.00 FL
2	1		*REAR BUMPER LOWER SKIRT	Distorted	710.00 FL	*710.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	650.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	90.00 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Missing	70.00 FL	*70.00 FL
6	1		*REAR TAILGATE	Bent	2,200.00 FL	*2,200.00 FL
7	1		*TAILGATE LOGO	Necessary	130.00 FL	*130.00 FL
8	1		*TAILGATE EMBLEM (TOURAN)	Necessary	190.00 FL	*190.00 FL
9	1		*TAILGATE EMBLEM (TDI)	Necessary	175.00 FL	*175.00 FL
10	1		*TAILGATE RH REFLECTOR	Broken	398.00 FL	*398.00 FL
11	1		*TAILGATE INNER RUBBER	Serviceable	580.00 FL	*- FL
12	1		*REAR WINDSCREEN GLASS	Shattered	1,390.00 FL	*1,390.00 FL
13	1		*REAR END PANEL	Repair	500.00 FL	*- FL
14	1		*TAILLAMP RH	Broken	560.00 FL	*560.00 FL
15	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
16	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,983.00	7,163.00
- List Item Discount on L Items 10.00/10.00% (\$)	874.30	692.30
Total Parts (\$)	8,108.70	6,470.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE & ATTACHMENT ,TO RENEW REAR PANEL ,KNOCK & REPAIR REAR RH FENDER AND REALIGN THE SAME	New	950.00	800.00
3	PUTTY & RESPRAY ON REAR END PANEL ,TAILGATE ,REAR BUMPER ,REAR RH SIDE PANEL	New	1,050.00	800.00
4	REMOVE & REFIX REVERSE CAMERA ,SENSOR ,SMART KEY AND RESET SYSTEM	New	40.00	40.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (\$\$)			2,220.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >