



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501368

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/03/2025
Reference CD/CTI24110440/Uma3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKA 8091Z
Insured Veh. SLR 8074Y
Claim No. SNM24D206359
Policy No. DMHCSNA00008862401
Accident Date 08/11/2024
Inspection Date 09/12/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24110440/Uma3q2(N)	
			Date: 10/03/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 8074Y	Veh. Inspected	SKA 8091Z
	Policy No.	DMHCSNA00008862401	Coverage (\$)	0.00
	Claim No.	SNM24D206359	Excess (\$)	0.00
	Assign From		Assign Date	09/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	OYOTA CAMRY 2.4 (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053BK4007034763	Colour	GOLD
	Odometer	904079 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	BLACKHAWK	6 mm
	L/H Front Tyre	215/60 R16	BLACKHAWK	6 mm
	R/H Rear Tyre	215/60 R16	BLACKHAWK	6 mm
	L/H Rear Tyre	215/60 R16	BLACKHAWK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/11/2024	Inspection Date	09/12/2024
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8091Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	1,255.60	-
1	BOOTLID REAR LOGO	SERVICEABLE	90.00	-
1	BOOTLID CAMRY EMBLEM	NOT NECESSARY	80.00	-
1	BOOTLID 2.4 EMBLEM	NOT NECESSARY	80.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	250.00	-
1	REAR BUMPER	DEFORMED / CRACKED	751.00	751.00
1	REAR BUMPER BEAM	BENT	480.00	480.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	680.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	422.60	-
1	REAR ANTENNA LOCK SENSOR	SERVICEABLE	280.00	-
1	TAILLAMP	SERVICEABLE	645.10	-
	LESS 25% DISCOUNT		-1,266.08	-320.25
			3,798.22	960.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REVERSE SENSOR .		80.00	30.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING .	NOT NECESSARY	60.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL .		800.00	400.00

Report Ref No. CD/CTI24110440/Uma3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
			2,010.00	1,050.00
GRAND TOTAL			6,088.22	2,010.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CD/CTI24110440/Uma3q2(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z




PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z



PHOTOGRAPHS FOR VEHICLE NO. : SKA 8091Z

