



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|-----------------------------------|-------|-----------------------|
| MS MS FIRST CAPITAL INSURANCE LTD | Ref: | CS/FCI24060288/Rvh3e2 |
| 16 RAFFLES QUAY | Date: | 27/06/2024 |
| #42-01 HONG LEONG BUILDING | Code: | FCI2 |
| SINGAPORE 048581 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHC 1467U | Veh. Inspected | SMR 9729Z |
| Policy No. | D-24101861MFCT | Coverage | 0 |
| Claim No. | D24005307MFCT | Excess | \$0.00 |
| Assign From | JOANNE TAN | Assign Date | 27/06/2024 |

2. Vehicle Details

| | | | |
|-----------------|------------------|--------------|------------|
| Make & Model | TOYOTA NOAH | C.C | 1797 |
| Engine No. | 2ZR2F93078 | Year of Reg. | 04/02/2020 |
| Chassis No. | ZWR800421770 | Colour | BLACK |
| Odometer | 160172 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|-----------|--------------|
| R/H Front Tyre | 195/65R15 | ROADSTONE | 6 |
| L/H Front Tyre | 195/65R15 | ROADSTONE | 6 |
| R/H Rear Tyre | 195/65R15 | ROADSTONE | 6 |
| L/H Rear Tyre | 195/65R15 | ROADSTONE | 6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 13/06/2024 | Inspection Date | 28/06/2024 |
| Survey held at | 61 WOODLANDS INDUSTRIAL PARK E9, E9 PREMIUM #01-29-1AXIS WORKSHOP PTE LTD | | |

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days