

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24110442/KPA3Q2**Date:** 07/02/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0005177  
**Claimant Vehicle No :** SME6590T **Insured Vehicle No :** GBM4560G  
 Date of Loss: 19/11/2024 Nature of Claim: TP Claim No: MFL2024D0013807

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME6590T**  
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6561174  
 Reg. Date: 10/10/2018 (Man. Year: 2018) Chassis No: GP71217425  
 Colour: Metallic Grey Odometer: 658054 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm  
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,930.64	6,161.32	1,769.32	22.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,590.00	1,020.00	39.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,540.64</b>	<b>7,751.32</b>	<b>2,789.32</b>	<b>26.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,540.64</b>	<b>6,200.00</b>	<b>4,340.64</b>	<b>41.18</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>6,587.25</b>		

INSPECTION

Date of Assignment: 21/11/2024  
 Date Inspected: 21/11/2024 Inspected At: Guan Motor Works (HQ)  
 176 Sin Ming Drive #02-03 Sin Ming Autocare  
 Singapore 575721  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Jan 2025)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME6590T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,150.60 FL	*1,150.60 FL
2	2		*REAR BUMPER SIDE REFLECTOR COVER	Serviceable	110.00 FL	*- FL
3	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	119.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Serviceable	57.00 FL	*- FL
5	2		*REAR BUMPER INNER SIDE FOAM	Cracked	113.00 FL	*113.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
7	1		*REAR TAILGATE	Bent	1,293.00 FL	*1,293.00 FL
8	2		*REAR TAILGATE SIDE LAMP	O/S Cut / N/S Cracked	790.00 FL	*790.00 FL
9	1		*REAR TAILGATE OUTER CHROME GARNISH /HANDLE	Warped	383.00 FL	*383.00 FL
10	2		*REAR TAILGATE NUMBER PLATE LAMP	Serviceable	96.00 FL	*- FL
11	1		*REAR TAILGATE REVERSE CAMERA	Dented / Shorted	920.00 FS	*380.00 FS
12	1		*REAR TAILGATE CENTRE H LOGO	Necessary	38.00 FL	*38.00 FL
13	1		*REAR TAILGATE LH SHUTTLE EMBLEM	Necessary	64.00 FL	*64.00 FL
14	1		*REAR TAILGATE RH HYBRID EMBLEM	Necessary	58.00 FL	*58.00 FL
15	1		*REAR TAILGATE TOP LOCK	Dented	157.00 FL	*157.00 FL
16	1		*REAR TAILGATE LOWER LOCK CATCH	Repair	27.50 FL	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP (50%)	Distorted / Dented	134.40 FS	*84.00 FS
18	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	320.00 FL	*320.00 FL
19	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*60.00 FL
20	1		*SET REAR TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
21	2		*TAILLAMP	Cut	1,040.00 FL	*1,040.00 FL
22	1		*REAR END PANEL	Bent	560.80 FL	*560.80 FL
23	1		*REAR END PANEL TOP GARNISH	Buckled	155.50 FL	*155.50 FL
24	1		*REAR END PANEL KEYLESS SENSOR	Cracked	85.00 FL	*85.00 FL
25	1		*REAR SPARE TYRE PANEL TOP BOARD	Dented	550.00 FL	*550.00 FL
26	1		*REAR LH FENDER INNER SIDE GARNISH	Serviceable	489.00 FL	*- FL
27	1		*SET REAR FENDER INNER SIDE GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
28	1		*FRONT TOP WINDSCREEN MOULDING	Not Necessary	59.50 FL	*- FL
29	1		*FRONT BOTTOM WINDSCREEN MOULDING	Not Necessary	36.90 FL	*- FL
30	1		*SET REVERSE SENSORS	Serviceable	280.00 FS	*- FS
31	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
32	1		*SET REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
33	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,537.20</b>	<b>7,556.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,606.56	1,395.58
<b>Total Parts (\$)</b>	<b>7,930.64</b>	<b>6,161.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,000.00	600.00
2	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
3	TO REMOVE ,REFIX REAR WINDSCREEN GLASS	New	140.00	120.00
4	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
5	TO REMOVE ,REFIT REVERSE SENSORS & REVERSE CAMERA	New	150.00	70.00
6	TO REMOVE ,REFIT REAR TAILGATE FITTINGS	New	80.00	60.00
7	TO REMOVE ,REFITREAR UPHOLSTERY & ATTACHMENTS	New	120.00	60.00
8	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,610.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >