源摩哆廠 GUAN MOTOR WORKS

源摩哆廠
GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 HVP. 9742 6003

5 day,

NOT Norhorsel

REPAIR ESTIMATE SME6590T

n Ming Drive #0	REPAIR ESTIMATE SME6590T) aay
No.	Qty	R. Joseph
	<u>List Items</u> \$	1,150.60
1	1 Rear bumper // The \$6	sen 110.00 X
2	2 Rear bumper side reflector cover	119.00 X
3	2 Rear bumper side reflector \$	57.00 ×
4	2 Pear humper side retainer	CM 113.00 2
5	2 Rear bumper inner side foam \$	Me 40.00
6	1 set Rear bumper clips \$	By 1,293.00
7	1 Rear tailgate NIJ CM	790.00
8		way 383.00 -
9	1 Poor tailgate outer chrome garrism/ name c	€ 96.00 ×
10	2 Rear tailgate number plate lamp	1,150.00 3805N
11	1 Paer tailgate reverse camera	Nec 38.00
12	a sample centre "H" logo	ne 64.00
13	4 Boor tailgate I H "SHUTTLE ellible"	s Ma 58.00
14	1 Rear tailgate RH "HYBRID" emblem	157.00
15	1 Poar tailgate top lock	27.50 X
16	1 Rear tailgate lower lock catch 841N	gis104 168.00 50 Nm
17	1 Poar tailgate weatherstrip	320.00 -
18	1 Pear tailgate inner trim board	5 Mc 60.00
19	1 act Poor tailgate inner trim board clips	5 Ma 120.00 —
20	1 set Rear tailgate windscreen moulding	\$ 67 1,040.00
21	2 Taillamp	\$ \$ 560.80
22	1 Rear end panel	\$ Bu 155.50
23	1 Rear end panel top garnish	\$ CM 85.00
24	1 Poar and nanel keyless sensor	\$ nd 550.00 2
25	1 Poor spare tyre panel top board	\$ 12 489.00 ×
26	1 Poor I H fender inner side gallisii	
27	1 cot Rear fender inner side garnish clips	\$ ~~ 60.00 \\ \$ ~~ 59.50 \(\times \)
28	1 Front ton windscreen mounting	\$ NN 36.90 X
29	1 Front bottom windscreen moulding	\$ 9,350.80
23	Less 20%	\$ 1,870.16
	Total :	\$ 7,480.64
	Total .	T
	Canadal Nott Items	B
	Special Nett Items	\$ 1280.00 X
30	1 set Reverse sensors	\$ Not 50.00 & 552 \$ Now 60.00 & 652 \$ May 60.00 3052
31	1 Rear number plate	\$ 104 60.00 4010
32	1 set Rear windscreen sealant	\$ Ma 60.00 30/n
33	1 set Rear end panel sealant Total :	\$ 450.00
	Labour	\$ 1,000.00 6001
	Labour Charges for remove/refit, cutting/welding and	
1	t of damages	\$ 1,000.00 6001
_	To putty and spray Spray Paintings Charges.	5 140.00 1201
2	To remove, refix rear windscreen glass.	5 40.00 201
3	inings and lightings.	\$ 1,000.00 8007 \$ 140.00 1201 \$ 40.00 201 \$ 150.00 701
4	To check wirings and lightings. To remove, refit reverse sensors & reverse camera.	\$ 130.00 700
5	10 femove, removed	

To remove, refit rear tailgate fittings.

To remove, refitrear upholstery & attachments.

To supply and apply anti rust treatment

Total: \$ 80.00 601

\$ 70.00 601

Total Parts and Labour : \$ 10,540.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: