



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBV 2699G

| REPLACEMENT OF PARTS | | | | |
|----------------------|-----------------------------|----------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | WINDSHIELD | SCRATCHED | \$485.00 | \$485.00 |
| 1 | CLUTCH LEVER | CRACKED | \$450.00 | \$200.00 |
| 1 | SIDE MIRROR | CUT | \$520.00 | \$180.00 |
| 1 | HANDLE BAR | BENT | \$680.00 | \$420.00 |
| 1 | HANDLE BAR END | CUT | \$280.00 | \$60.00 |
| 1 | SET HAND GRIP | SERVICEABLE | \$155.00 | \$0.00 |
| 1 | FRONT FOOTREST - L/H | SERVICEABLE | \$320.00 | \$0.00 |
| 1 | FRONT FOOTREST BRACKET | NOT NECESSARY | \$755.00 | \$0.00 |
| 2 | REAR FOOTREST | SERVICEABLE | \$280.00 | \$0.00 |
| 1 | REAR FOOTREST BRACKET | CUT | \$680.00 | \$290.00 |
| 1 | EXHAUST ASSY | DENTED/DAMAGED | \$2,800.00 | \$1,800.00 |
| 1 | SET REAR SIGNALS | CRACKED | \$420.00 | \$120.00 |
| 1 | ENGINE COVER | CUT | \$1,280.00 | \$900.00 |
| | LESS 10.00% DISCOUNT | | (\$910.50) | (\$445.50) |
| | | | \$8,194.50 | \$4,009.50 |

| Special Nett | | | | |
|--------------|----------------------------|-----------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | SET REAR NUMBER PLATE (SN) | BENT | \$38.00 | \$20.00 |
| | | | \$38.00 | \$20.00 |

| Labour | | | | |
|--------|---|---------------|------------------------|-------------------|
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | TO CHECK WIRING AND RESET HEADLAMP FOCUSING | NOT NECESSARY | \$80.00 | \$0.00 |
| | TO REPAIR BODY FRAME | NOT NECESSARY | \$580.00 | \$0.00 |
| | TO PROVIDE LABOUR AND REPAIR FRONT FORK | | \$680.00 | \$380.00 |
| | | | \$1,340.00 | \$380.00 |

| | | | | |
|--------------------|--|--|-------------------|-------------------|
| GRAND TOTAL | | | \$9,572.50 | \$4,409.50 |
|--------------------|--|--|-------------------|-------------------|

| | | | | |
|--|---|--|--|-------------------|
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | \$3,500.00 |
|--|---|--|--|-------------------|

Report Ref No: CS/INC24110447/Uvh3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

TOTAL FOR SPARE PARTS: \$ 8,232.50 \$ 4,029.50
TOTAL FOR LABOUR : \$ 1,340.00 \$ 380.00
TOTAL REPAIR COST: \$ 9,572.50 \$ 4,409.50

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.