

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24110450/RVP3E2**Date:** 27/02/2025REFERENCE

Insured/Claimant:	TAN WANG CHEOW	Policy No:	1800129508-06	
Date of Loss:	20/11/2024	Nature of Claim:	OD	Claim No: 3193873875SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9900C		
Make & Model:	AUDI A5, 2.0 (A)	Engine No:	CVK067574
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF5XJA129733
Colour:	Black	Odometer:	51492 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,257.00	16,535.76	16,721.24	50.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	29,792.00	9,392.00	20,400.00	68.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	63,049.00	25,927.76	37,121.24	58.88
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	61,449.00	24,327.76	37,121.24	60.41
+ GST 9.00/9.00% (\$\$)	5,530.41	2,189.50	3,340.91	60.41
Nett Amount (\$\$)	66,979.41	26,517.26	40,462.15	60.41

INSPECTION

Date of Assignment:	21/11/2024	
Date Inspected:	22/11/2024	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,397.00 FS	*2,717.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	292.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	280.00 FS	*223.60 FS
4	1		*REAR BUMPER CHROME TRIM	Cracked	1,267.00 FS	*1,013.60 FS
5	1		*REAR LIGHT REFLECTOR - LH	Not Necessary	49.00 FS	*- FS
6	1		*LED TAIL LIGHT - LH OUTER	Not Necessary	1,427.00 FS	*- FS
7	1		*LED TAIL LIGHT TRIM - LH OUTER	Scratched	41.00 FS	*32.40 FS
8	1		*LED TAIL LIGHT - LH INNER	Cracked	1,276.00 FS	*1,020.80 FS
9	1		*LED TAIL LIGHT TRIM - LH INNER	Missing	41.00 FS	*32.40 FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	1,297.00 FS	*1,037.60 FS
11	2		*REAR BUMPER REINFORCEMENT BEAM SEAL	Cut	36.00 FS	*28.80 FS
12	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	56.00 FS	*- FS
13	2		*REAR BUMPER GUIDE SECTION - LH / RH	Damaged	58.00 FS	*45.44 FS
14	2		*REAR BUMPER GUIDE SECTION PIN - LH / RH	Not Necessary	7.00 FS	*- FS
15	1		*REAR PARKING AID SENSOR (2PCS)	Distorted (1Pc Only)	572.00 FS	*228.80 FS
16	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
17	1		*SET REAR BUMPER WIRING	Not Necessary	796.00 FS	*- FS
18	1		*REAR LID OPENING CONTROL UNIT	Not Necessary	617.00 FS	*- FS
19	1		*REAR LID OPENING CONTROL UNIT RETAINER	Not Necessary	10.00 FS	*- FS
20	1		*REAR LID OPENING SENSOR LINE	Not Necessary	244.00 FS	*- FS
21	1		*AERIAL FOR ACCESS AND START AUTHORISATION	Not Necessary	129.00 FS	*- FS
22	1		*AERIAL RETAINER	Not Necessary	32.00 FS	*- FS
23	1		*TELEPHONE AERIAL	Not Necessary	207.00 FS	*- FS
24	1		*REAR LID	Bent	4,586.00 FS	*3,668.80 FS
25	1		*AUDI EMBLEM	Necessary	183.00 FS	*146.00 FS
26	1		*A5 EMBLEM	Necessary	116.00 FS	*92.80 FS
27	1		*TFSI EMBLEM	Necessary	116.00 FS	*92.80 FS
28	2		*REAR LID HINGE - LH / RH	Not Necessary	568.00 FS	*- FS
29	1		*REAR LID ATTACHMENT PARTS	Not Necessary	171.00 FS	*- FS
30	1		*REAR LID WEATHER STRIP	Deformed	294.00 FS	*234.80 FS
31	1		*REAR LID PACKING ADHESIVE	Necessary	23.00 FS	*18.32 FS
32	1		*REAR FENDER - LH	Repair	5,180.00 FS	*- FS
33	1		*REAR QUARTER GLASS - LH	Not Necessary	896.00 FS	*- FS
34	2		*PRIMER	Damaged	54.00 FS	*21.68 FS
35	1		*REAR WINDSCREEN	Necessary	1,463.00 FS	*1,170.40 FS
36	1		*THIRD BRAKE LIGHT	Necessary	782.00 FS	*625.60 FS
37	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	332.00 FS	*- FS
38	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	153.00 FS	*- FS
39	1		*SIDE MEMBER TRIM ATTACHMENT PARTS - LH	Not Necessary	153.00 FS	*- FS
40	1		*SIDE MEMBER TRIM ADHESIVE TAPES - LH	Not Necessary	233.00 FS	*- FS
41	1		*REAR CROSS PANEL	Bent	414.00 FS	*331.20 FS
42	1		*REAR CROSS PANEL REINFORCEMENT BEAM	Bent	730.00 FS	*583.60 FS
43	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
44	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
45	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
46	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
47	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
48	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
49	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
50	1		*SUNDRIES	Necessary	800.00 FS	*6.72 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*TRIM FOR REAR END PANEL PANELLING (Supplementary)	Cracked	441.00 FS	*352.40 FS
52	1		*REAR LID ABSORBER LHS (Supplementary)	Squeeking	2,287.00 FS	*1,829.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					33,257.00	16,535.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	780.00	480.00
3	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,600.00	1,600.00
4	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC	New	1,600.00	0.00
5	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. TRANSFER OLD FITTINGS AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	13,000.00	2,750.00
6	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR, DOOR ENTRANCE, SPARE WHEEL HOUSING, DRAIN PANEL, ROOF CHANNEL AND END PANELLING	New	11,000.00	2,750.00
7	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	400.00
8	TO CARRY OUT WATER SEEPAGE TEST FOR AFFECTED GLASSES	New	280.00	280.00
9	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			29,792.00	9,392.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >