

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ4923

Regn: 2010, July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki APV

C.D.

1590

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 312566

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHY6DN71V00302398

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hubileed

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.A. 12/11/24

Survey held at Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG.

COE Expiry: 31/12/2024

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 131k Depreciation @ 10% x 15

PV: 500

Nett: 800

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + R. \$1

Photos

Others

Add Fee: _____



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)

Report Form: _____

Report Form: _____

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : SMQ 4923 S

MAKE / MODEL : SUZUKI APV

CHASSIS NO : MHYGDN71V00302398

ACCIDENT DATE : 29.10.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)	
<u>LIST ITEMS</u>				
1	Rear tailgate <i>Dented</i>	1	\$	<i>✓</i> 895.20
2	Rear tailgate S logo	1	\$	<i>✓</i> 30.00
3	Rear tailgate APV emblem <i>2 per</i>	1	\$	<i>✓</i> 17.94
			\$	943.14
			LESS 15% DISC	\$ 141.471
			TOTAL	\$ 801.67

LABOUR COST				
1	To supply rear windscreen sealant	1	\$	✓ 50.00
2	Remove + reinstall rear windscreen	1	\$	120 150.00
3	Remove, replace + repair consistant to the accident repair	1	\$	2w 800.00
4	Reapray painting	1	\$	2w 400.00
			TOTAL	\$ 1400.00
			GRAND TOTAL	\$ 2201.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin
1/5 12/11/24
03 Days