



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JPX 377

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER	BROKEN	425.00	160.00
2	FORK TUBE ASSY	BENT/TWISTED	3,600.00	1,300.00
1	FORK UNDER BRACKET	BENT/TWISTED	1,285.00	280.00
1	FRONT RIM SHAFT	SERVICEABLE	125.00	-
1	FRONT RIM BEARING	NOT NECESSARY	95.00	-
1	FRONT BRAKE DISC	SERVICEABLE	850.00	-
1	FUEL TANK	BENT/DENTED	2,050.00	1,480.00
1	TOP COWLING	CUT	945.00	305.00
1	WINDSCREEN	BROKEN	360.00	180.00
1	LAMP STAY	BENT	730.00	160.00
1	HEADLAMP - LED	CRACKED	1,850.00	1,050.00
1	METER ASSY	NOT NECESSARY	1,850.00	-
2	SET SIDE MIRROR	NOT NECESSARY	530.00	-
2	SET HANDLE-BAR	SERVICEABLE	710.00	-
2	SET HANDLE-BAR END	NOT NECESSARY	170.00	-
1	SET HAND GRIP	NOT NECESSARY	75.00	-
1	CLUTCH LEVER	CUT	185.00	90.00
1	SET FRONT SIGNALS	CUT	400.00	120.00
1	SET SIDE FAIRING	CRACKED	1,610.00	820.00
1	SIDE FAIRING INNER PANEL - L/H	CRACKED	180.00	60.00
1	SIDE FAIRING LOWER COVER	NOT NECESSARY	480.00	-
1	SIDE FAIRING CENTRE COVER	NOT NECESSARY	185.00	-
1	RADIATOR	BENT/PUNCTURE	1,848.00	800.00
2	FRONT FOOTRESTS	NOT NECESSARY	190.00	-
2	FRONT FOOTRESTS BRACKETS	NOT NECESSARY	290.00	-
1	GEAR PEDAL	CUT	225.00	105.00
2	SET REAR FOOTREST	NOT NECESSARY	310.00	-
2	SET REAR FOOTREST BRACKET	NOT NECESSARY	640.00	-
	LESS 10% DISCOUNT		-2,219.30	-691.00
			19,973.70	6,219.00

Report Ref No. CS/FCI24110455/Uqp3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	FRONT MISSING	38.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	40.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	76.00	-
1	SET STEERING CONE (SN)	NECESSARY	120.00	60.00
1	GASKET (SN)	NOT NECESSARY	150.00	-
3	ENGINE OIL (SN)	NOT NECESSARY	84.00	-
1	FRONT REFLECTOR (SN)	NOT NECESSARY	80.00	-
			588.00	70.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	420.00	-
	TO PROVIDE LABOUR.		480.00	300.00
			980.00	300.00
<b>GRAND TOTAL</b>			<b>21,541.70</b>	<b>6,589.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,200.00</b>

Report Ref No. CS/FCI24110455/Uqp3m4(N)

MARKET VALUE: RM7,400.00 (EST)

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.