



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4744H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT HEADLAMP R/L	O/S CUT	4,539.40	2,269.70
4	FRONT HEADLAMP LOWER CLIP HOLDER R/L	O/S DAMAGED	28.00	19.00
1	FRONT GRILLE	CRACKED	573.30	573.30
1	FRONT BUMPER	DISTORTED	665.00	495.00
2	FRONT BUMPER SIDE RETAINER R/L	O/S CRACKED	60.00	30.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	497.00	-
1	FRONT BUMPER LOGO 'kia'	NECESSARY	38.00	38.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	438.00	210.00
1	FRONT BUMPER LOWER REINFORCEMENT	NOT NECESSARY	125.40	-
1	FRONT BUMPER INNER SPONGE	CRACKED	92.40	92.40
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	15.00	-
2	FRONT BUMPER FOGLAMP R/L	O/S MISSING	666.00	333.40
2	FRONT BUMPER FOGLAMP COVER R/L	O/S MISSING	78.00	39.00
1	FRONT BUMPER UPPER COVER	NOT NECESSARY	49.00	-
2	FRONT BUMPER LAMP COVER R/L	NOT NECESSARY	86.00	-
2	FRONT BUMPER LAMP COVER AIR DUCT GARNISH R/L	NOT NECESSARY	60.00	-
1	FRONT SUPPORT PANEL	CRACKED	695.00	695.00
1	FRONT WASHER TANK	NOT NECESSARY	166.00	-
1	FRONT FENDER R	BUCKLED	593.00	593.00
2	FRONT FENDER INNER SHIELD R/L	NOT NECESSARY	198.00	-
1	FRONT SPORT RIM LH	NOT NECESSARY	817.00	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	308.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	126.00	-
1	FRONT LOWER ARM LH	NOT NECESSARY	368.50	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	408.10	-
1	FRONT KNUCKLE ARM BEARING HUB LH	NOT NECESSARY	456.00	-
1	FRONT WIRING HARNESS	SNAPPED	810.40	520.00
	LESS 10% DISCOUNT		-1,295.65	-590.78
			11,660.85	5,317.02

Report Ref No. CS/INC24110458/Aqh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
2	SETS FRONT FENDER INNER SHIELD CLIP R/L (SN)	NOT NECESSARY	100.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	280.00	-
			460.00	30.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA.		1,000.00	600.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA.		800.00	400.00
	TO REMOVE & REFIX AIR-CON CONDENSER, HOSE, PIPE VACUUM & REFILING GAS.		150.00	60.00
	TO REMOVE & REFIX RADIATOR, FAN MOTOR & OTHER ATTACHMENT PARTS.		100.00	60.00
	TO COMPUTERISE WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CHECK WIRING.		80.00	30.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-
			2,370.00	1,150.00
GRAND TOTAL			14,490.85	6,497.02

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,200.00
---	--	--	-----------------

Report Ref No. CS/INC24110458/Aqh3e2(N)

TOTAL FOR SPARE PARTS: \$ 12,120.85 \$ 5,347.02

TOTAL FOR LABOUR : \$ 2,370.00 \$ 1,150.00

TOTAL REPAIR COST: \$ 14,490.85 \$ 6,497.02

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.