



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBR 90X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAIL LAMP LOWER GARNISH R	TORN	372.00	372.00
1	REAR TAIL LAMP LOWER GARNISH RETAINER R	NOT NECESSARY	139.90	-
1	REAR BUMPER	NOT NECESSARY	2,929.40	-
	LESS 25% DISCOUNT		-860.33	-93.00
			2,580.97	279.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER LOWER LID SPOILER (SN)	TO REPAIR SEE LABOUR	800.00	-
			850.00	-
	<u>LABOUR</u>			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER LID SPOILER.		400.00	200.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA.		400.00	300.00
	TO CHECK WIRING & REWIRE PARKING SENSOR.	NOT NECESSARY	500.00	-
			1,300.00	500.00
	GRAND TOTAL		4,730.97	779.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			600.00

Report Ref No. CS/INC24110459/Avh3e2(N)

TOTAL FOR SPARE PARTS: \$ 3,430.97 \$ 279.00

TOTAL FOR LABOUR : \$ 1,300.00 \$ 500.00

TOTAL REPAIR COST: \$ 4,730.97 \$ 779.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.