



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3138G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR LAMP LH	CRACKED	512.60	398.00
1	REAR CORNER PANEL LH	DENTED	570.60	195.00
1	REAR BUMPER ASSY	CUT	591.70	591.70
1	REAR BUMPER SIDE HOLDER LH	NOT NECESSARY	68.50	-
	LESS 25% DISCOUNT		-435.85	-296.18
			1,307.55	888.52
	<b><u>SPECIAL NETT ITEMS</u></b>			
8	REAR BUMPER CLIPS @\$5.71 (SN)	NECESSARY	45.68	30.00
			45.68	30.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.		800.00	200.00
	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING.		80.00	30.00
	TO PUTTY AND RESPRAY PAINTING ON REAR FENDER LH, CORNER PANEL.		800.00	300.00
			1,680.00	530.00
	<b>GRAND TOTAL</b>		<b>3,033.23</b>	<b>1,448.52</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)</b>			<b>1,150.00</b>
--	--	--	-----------------

Report Ref No. CS/INC24110460/Avh3e2(N)

TOTAL FOR SPARE PARTS: \$ 1,353.23 \$ 918.52

TOTAL FOR LABOUR : \$ 1,680.00 \$ 530.00

TOTAL REPAIR COST: \$ 3,033.23 \$ 1,448.52

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.