



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JEFF LIN

Ref: CS/INC24110460/Avh3e2(N)

Date: 24/04/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 5759B	Veh. Inspected	GBG 3138G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302800-002	Excess (\$)	0.00
Assign From	JEFF LIN	Assign Date	20/11/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2010202607	Colour	SILVER
Odometer	209307 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	GITI	6 mm
L/H Front Tyre	195 R15C	GITI	6 mm
R/H Rear Tyre	195 R15C	GITI	6 mm
L/H Rear Tyre	195 R15C	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2024	Inspect Date / Time	21/11/2024 (02:45 PM)
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**