

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURANCE		Ref:	CS/INC24060029/Avp3m4	
IVIO	75 BRAS BASAH RO		Date:	26/08/2024	
		SINGAPORE 189557			
			Code:	INC	
1.	,				
	Insured Veh.	SKR 2029E	Veh. Inspected	SFQ 619E	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1281124-002	Excess	\$0.00	
	Assign From	FIONA SHEN	Assign Date	11/06/2024	
2.					
	Make & Model	TOYOTA COROLLA ALTIS	C.C	1598	
	Engine No.	1ZRX039072	Year of Reg.	08/12/2010	
	Chassis No.	MR053REE104105394	Colour	BLACK	
	Odometer	169830 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	BRIDGESTONE	6	
	L/H Front Tyre	195/65R15	BRIDGESTONE	6	
	R/H Rear Tyre	195/65R15	BRIDGESTONE	6	
	L/H Rear Tyre	195/65R15	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	09/06/2024	Inspection Date	11/06/2024 (17:05)	
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days