



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24110462/Anh3m4(N)

Date: 25/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9864Z	Veh. Inspected	SMY 6303B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302198-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	21/11/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER HYBRID	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	AXUH800010209	Colour	GREY
Odometer	107662 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65R17	YOKOHAMA	6 mm
L/H Front Tyre	225/65R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/65R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/65R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2024	Inspect Date / Time	25/11/2024 (05:36 PM)
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**