

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 6320C

Estimate By Our Adjusted Qty **Description of Parts** Condition Workshop (\$)) (\$) REPLACEMENT OF PARTS 1 REAR BUMPER **DEFORMED** 1,294.21 1,294.21 2 REAR BUMPER SIDE GUIDE LH & RH @\$142.55 NOT NECESSARY 285.10 99.32 1 REAR BUMPER CENTER GUIDE **CRACKED** 99.32 1 REAR BUMPER ADAPTER NOT NECESSARY 81.20 1 REAR BUMPER TOW COVER **DEFORMED** 54.50 54.50 2 REAR BUMPER REFLECTOR LH & RH @\$42.57 **CRACKED** 85.14 85.14 REAR BUMPER NUMBER PLATE LAMP LH & RH @\$72.60 **CRACKED** 145.20 145.20 REAR BUMPER REINFORCEMENT **DENTED** 423.88 423.88 4 REAR BUMPER PDC SENSOR @\$268.10 DAMAGED (2PCS 1,072.40 536.20 ONLY) 4 REAR BUMPER PDC SENSOR HOLDER @\$58.60 NECESSARY (2PCS 234.40 50.00 ONLY) 4 REAR BUMPER PDC SENSOR DECOUPING RING @ NECESSARY (2PCS 53.60 26.80 ONLY) \$13.40 1 REAR SMART LOCK ANTENNA NOT NECESSARY 116.34 1 REAR END PANEL TO REPAIR SEE 547.20 **LABOUR** 1 REAR END PANEL TOP GARNISH **DEFORMED** 116.15 116.15 1 REAR FLOOR PANEL NOT NECESSARY 462.42 1 REAR FLOOR PANEL TOP PANEL NOT NECESSARY 216.78 2 REAR FENDER LH & RH (NPA) NOT NECESSARY **NOT NECESSARY** 2 REAR FENDER INNER TRIMBOARD LH & RH @\$528.55 1,057.10 2 REAR TAILLAMP LH & RH @\$425.04 **CRACKED** 850.08 850.08 DENTED REAR TAIL GATE 1.337.91 1.337.91 1 REAR TAILGATE 'LOGO' EMBLEM **NECESSARY** 108.57 108.57 2 REAR TAILGATE REFLECTOR LAMP LH & RH @\$352.55 **CRACKED** 705.10 705.10 1 REAR TAILGATE HANDLE SWITCH NOT NECESSARY 108.92 1 REAR TAILGATE INNER LOCK DAMAGED 188.58 188.58 1 REAR TAILGATE INNER TRIMBOARD **DEFORMED** 278.25 278.25 1 REAR TAILGATE WEATHER STRIP NOT NECESSARY 97.02 REAR EXHAUST MUFFLER NOT NECESSARY 1.001.76 1 REAR EXHAUST MUFFLER TAILPIPE END NOT NECESSARY 118.64

Report Ref No. CS/LPC24110463/Avh3e2(N)

Page No.:1 of 3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	73.92	-
	LESS 10% DISCOUNT		-	-629.99
			11,213.69	5,669.90
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET REAR TAIL GATE INNER TRIMBOARD CLIPS (SN)	NECESSARY	60.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	60.00	20.00
2	SETS REAR FENDER INNER TRIMBOARD CLIPS LH & RH (SN)	NOT NECESSARY	120.00	-
2	TUBES PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
2	TUBES REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	120.00	60.00
			590.00	190.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE AND PANEL BEATING AT AFFECTED PARTS FOR REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL,		1,500.00	600.00
	TO SPRAY PAINT ON AFFECTED AREA AT REAR PORTION.		1,500.00	600.00
	TO REMOVE / REPLACE / REINSTALL TAILGATE TRIM & COMPONENTS.		150.00	60.00
	TO REMOVE / REPLACE / REINSTALL REAR PANEL UPHOLSTERY & TRIM.		200.00	40.00
	TO REMOVE / REPLACE / REINSTALL REAR WINDSCREEN GLASS.		200.00	120.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.		200.00	30.00
	TO REMOVE / REPLACE / REINSTALL REVERSE SENSORS.		100.00	50.00
	TO CHECK WIRING FOR REAR PORTION.		60.00	30.00
	TO PERFORM SYSTEM DIAGNOSTIC & RESET ECU SYSTEM.		400.00	120.00
			4,310.00	1,650.00
	GRAND TOTAL		16,113.69	7,509.90

Report Ref No. CS/LPC24110463/Avh3e2(N)



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		6,000.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/LPC24110463/Avh3e2(N)

MARKET VALUE: \$21,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,701.00=NETT VALUE: \$9,299.00



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.