



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 813E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	280.00	-
1	HANDLE-BAR	BENT	220.00	168.00
1	HANDLE BAR INNER BRACKET	NOT NECESSARY	200.00	-
1	SET HANDLE-BAR END	CUT	120.00	40.00
1	SET HAND GRIP	NOT NECESSARY	95.00	-
1	HEADLAMP	SCRATCHED	480.00	380.00
1	SET SIDE MIRROR	CUT	140.00	60.00
1	BRAKE LEVER	CUT	125.00	125.00
1	SET FAIRING ASSY	CRACKED / CUT	625.00	625.00
1	FRONT FOOTREST BRACKET	BENT	280.00	126.00
2	FRONT FOOTREST RUBBERS	TORN / NECESSARY	100.00	60.00
1	BRAKE PEDAL	CUT	220.00	125.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	1,800.00	-
1	EXHAUST PROTECTOR	CUT	165.00	148.00
1	REAR RIM	TO REPAIR SEE LABOUR	580.00	-
1	REAR REFLECTOR	BROKEN	145.00	45.00
1	REAR SWING ARM	BENT / TWISTED	685.00	685.00
1	REAR LAMP	CRACKED	385.00	280.00
1	REAR FENDER	CRACKED	285.00	140.00
2	REAR FOOTRESTS	SERVICEABLE	180.00	-
2	REAR FOOTREST BRACKETS	O/S CRACKED	420.00	110.00
	LESS 10% DISCOUNT		-817.00	-311.70
			7,353.00	2,805.30
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR NUMBER PLATE (SN)	BENT	38.00	20.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-

Report Ref No. CS/INC24110470/Unh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	150.00	-
1	STICKER (SN)	NECESSARY	120.00	60.00
1	REAR BOX (SN)	CUT	480.00	400.00
1	REAR BOX BRACKET (SN)	SERVICEABLE	180.00	-
			1,054.00	480.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	520.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY AND REAR RIM.		420.00	300.00
			1,020.00	300.00
GRAND TOTAL			9,427.00	3,585.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,600.00

Report Ref No. CS/INC24110470/Unh3e2(N)

TOTAL FOR SPARE PARTS: \$ 8,407.00 \$ 3,285.30

TOTAL FOR LABOUR : \$ 1,020.00 \$ 300.00

TOTAL REPAIR COST: \$ 9,427.00 \$ 3,585.30

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.