

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110471/RUA3Q2
Date: 09/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : SKX6078E Insured Vehicle No : GBM120U
Date of Loss: 19/11/2024 Nature of Claim: TP Claim No: MFL2024D0013797

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX6078E
Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16976212B
Reg. Date: 21/12/2015 (Man. Year: 2015) Chassis No: MNTBBAB17Z0025145
Colour: Grey Odometer: 108906 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,850.69	2,367.89	1,482.80	38.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,373.00	5,633.00	740.00	11.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,223.69	8,000.89	2,222.80	21.74
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	10,223.69	5,500.00	4,723.69	46.20
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/11/2024
Date Inspected: 22/11/2024 Inspected At: Tan Chong Motor Sales Pte Ltd (HQ)
913 Bukit Timah Road
Singapore 589623
Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2024)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX6078E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Shorted	144.85 FS	*144.85 FS
2	1		*W/STRIP T/LID	Necessary	92.50 FN	*92.50 FN
3	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
4	1		*BRACKET LH	*Check	37.40 FN	*- FN
5	1		*BRACKET RH	*Check	37.40 FN	*- FN
6	1		*PLATE LUGGAGE	*Check	80.00 FN	*- FN
7	1		*CARPET-LUGGAGE	*Check	462.50 FN	*- FN
8	1		*SPACER	*Check	172.40 FN	*- FN
9	1		*TRUNK LID	Bent	780.20 FN	*780.20 FN
10	1		*FINISHER ASSY	Cracked	186.70 FN	*186.70 FN
11	1		*LOCK ASSY -TRUNK	*Check	78.90 FN	*- FN
12	1		*PANEL -REAR UPPER	Bent	445.50 FN	*445.50 FN
13	1		*ENERGY ABS RH	*Check	94.60 FN	*- FN
14	1		*ENERGY ABS LH	*Check	141.90 FN	*- FN
15	1		*ENERGY ABS	*Check	37.90 FN	*- FN
16	1		*BUMPER	Deformed	833.10 FN	*833.10 FN
17	1		*LAMP COMB RR LH	*Check	153.60 FN	*- FN
18	1		*LAMP COMB RR LH	Cracked	403.30 FN	*403.30 FN
19	1		*LAMP COMB RR RH	*Check	153.60 FN	*- FN
20	1		*LAMP COMB RR RH	*Check	403.30 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,769.65	2,916.15
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	918.96	548.26
Total Parts (\$\$)	3,850.69	2,367.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/INSTALL OR RENEW REVERSE CAMERA ASSIST TO REPAIR	New	120.00	120.00
2	REMOVE /INSTALL SEAT & CUSHION CARPET	New	240.00	240.00
3	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	360.00	240.00
4	REPLACE REVERSE SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
5	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	200.00	200.00
6	CHECK LIGHTING	New	48.00	48.00
7	TRANSFER MECHANISM PART FOR TRUNKLID	New	60.00	60.00
8	REPAIR RH/LH RR FENDER ,RR FLOOR PANEL RENEW RR BUMPER & TAILGATE	New	3,010.00	2,580.00
9	S/PAINT RR BUMPER ,TRUNK LID RR/LH RR FENDER ,RR END PANEL ,RR FLOOR PANEL	New	2,280.00	2,090.00
Gross Labour Cost (\$\$)			6,373.00	5,633.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >