



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SU 5520L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	CUT	209.00	95.00
1	FRONT FORK ASSY	BENT	1,116.00	680.00
1	FRONT FORK BRACKET	BENT	291.00	110.00
1	HEADLAMP	NOT NECESSARY	638.00	-
1	HEADLAMP COWLING	NOT NECESSARY	211.00	-
1	HEADLAMP COWLING SIDE GARNISH	CUT	235.00	235.00
1	SIDE COWLING	CUT	387.00	250.00
1	SIDE COWLING SIGNAL LAMP	SMASHED	55.00	55.00
1	HANDLE BAR	BENT	158.00	158.00
1	HANDLE LEVER	CUT	49.00	49.00
1	FRONT WING MIRROR	CUT	89.00	65.00
1	BALANCER	CUT	45.00	45.00
1	FOOT LEVER	CUT	75.00	75.00
1	FRONT FOOTREST	CRACKED	53.00	53.00
1	FRONT FOOTREST BRACKET	NOT NECESSARY	144.00	-
1	MAIN STAND	CUT	185.00	185.00
1	REAR FOOTREST	CUT	53.00	53.00
1	REAR FOOTREST BRACKET	CUT	149.00	149.00
1	REAR SIDE COWLING	CUT	262.00	180.00
	LESS 10% DISCOUNT		-440.40	-243.70
			3,963.60	2,193.30
	<u>SPECIAL NETT ITEMS</u>			
1	FORK OIL (SN)	NECESSARY	30.00	30.00
1	FORK OIL SEAL (SN)	NECESSARY	56.00	56.00
1	STEERING CONE & BEARING (SN)	NECESSARY	98.00	98.00
1	ERP UNIT (SN)	NOT NECESSARY	180.00	-
1	ERP UNIT COVER (SN)	TORN	25.00	25.00
1	REAR BOX (SN)	CUT	280.00	250.00
1	REAR BOX BRACKET (SN)	BENT	250.00	200.00
			919.00	659.00

Report Ref No. CS/INC24110475/Avh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00
	TO REPAIR & STRAIGHTEN BODY CHASSIS.	NOT NECESSARY	250.00	-
	TOWING FEES.		40.00	40.00
			1,140.00	470.00
	GRAND TOTAL		6,022.60	3,322.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,600.00

Report Ref No. CS/INC24110475/Avh3e2(N)

TOTAL FOR SPARE PARTS: \$ 4,882.60 \$ 2,852.30

TOTAL FOR LABOUR : \$ 1,140.00 \$ 470.00

TOTAL REPAIR COST: \$ 6,022.60 \$ 3,322.30

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.