

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #01-77 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

TEL: 92327457

TP INC
VERON.

TO	: NTUC	DATE	2/11/2024
VEHICLE NO	: SU5520L		
VEHICLE MODEL	: HONDA RS-X		
CHASSIS NO	: PMKKC43E0PB120454		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	FRONT FENDER <i>lt</i>		209.00	95
2	FRONT FORK ASSY <i>Bent</i>		1116.00	680
3	FRONT FORK BRACKET <i>Bent</i>		291.00	110
4	HEADLAMP <i>New</i>		638.00	X
5	HEADLAMP COWLING <i>New</i>		211.00	X
6	HEADLAMP COWLING SIDE GARNISH <i>lt</i>		235.00	✓
7	SIDE COWLING <i>lt</i>		387.00	250
8	SIDE COWLING SIGNAL LAMP <i>Smashed</i>		55.00	✓
9	HANDLE BAR <i>Bent</i>		158.00	✓
10	HANDLE LEVER <i>lt</i>		49.00	✓
11	FRONT WING MIRROR <i>lt</i>		89.00	65
12	BALANCER <i>lt</i>		45.00	✓
13	FOOT LEVER <i>lt</i>		75.00	✓
14	FRONT FOOTREST <i>cracked</i>	2437	53.00	✓
15	FRONT FOOTREST BRACKET <i>Not rec</i>	2193.30	144.00	X
16	MAIN STAND <i>lt</i>		185.00	✓
17	REAR FOOTREST <i>lt</i>		53.00	✓
18	REAR FOOTREST BRACKET <i>lt</i>		149.00	✓
19	REAR SIDE COWLING <i>lt</i>		262.00	180
			4404.00	
Less 10%			440.40	10%
			3963.60	
<u>SPECIAL NETT ITEMS</u>				
1	FORK OIL <i>✓</i>		30.00	✓
2	FORK OIL SEAL <i>✓</i>		56.00	✓
3	STEERING CONE & BEARING <i>✓</i>		98.00	✓
4	ERP UNIT <i>New</i>		180.00	X
5	ERP UNIT COVER <i>torn</i>		25.00	✓
6	REAR BOX <i>lt</i>		280.00	250
7	REAR BOX BRACKET <i>Bent</i>		250.00	200
Total Parts			919.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	400.00	200
2	SPRAY PAINTING	400.00	200
3	WIRING	50.00	30
4	TO REPAIR & STRAIGHTEN BODY CHASSIS	250.00	+
5	TOWING FEES	40.00	✓
	Labour Total :	1140.00	
	TOTAL (PARTS & LABOUR):	6022.60	

470

Total: 3322.30

h/s: 2.61c.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: