

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110476/APA3Q2**Date:** 17/03/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070132586
Claimant Vehicle No : SKU1350S **Insured Vehicle No :** SMV1657D
 Date of Loss: 15/11/2024 Nature of Claim: TP Claim No: 1866412441SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU1350S**
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B3521486
 Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: RU11021470
 Colour: Blue Odometer: 202776 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,849.52	5,290.00	8,559.52	61.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,020.00	1,830.00	3,190.00	63.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,869.52	7,120.00	11,749.52	62.27
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	18,869.52	5,600.00	13,269.52	70.32
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,227.25		

INSPECTION

Date of Assignment: 18/11/2024
 Date Inspected: 18/11/2024 Inspected At: Kt Motorwerk (HQ)
 Estimated Period of Repair: 6.0 days Blk 3012 Bedok Industrial Park E, #01-2020
 Singapore 489978

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,723.20 FL	*1,100.00 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	398.80 FL	*- FL
3	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
4	1		*TAILGATE BADGE	Not Necessary	98.60 FL	*- FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	95.70 FL	*95.70 FL
6	1		*TAILGATE LAMPS	RH Cut	997.20 FL	*412.00 FL
7	1		*TAILGATE LAMP INNER SEALER	Not Necessary	40.00 FL	*- FL
8	1		*TAILGATE LAMP CLIPS (1 SET)	Not Necessary	30.00 FL	*- FL
9	2		*TAILGATE STOPPER	Not Necessary	60.00 FL	*- FL
10	1		*TAILGATE POCKET HANDLE	Not Necessary	75.20 FL	*- FL
11	1		*TAILGATE INNER TRIM	Cracked	487.60 FL	*285.00 FL
12	1		*TAILGATE INNER TRIM CLIPS (1 SET)	Necessary	30.00 FL	*30.00 FL
13	1		*TAILGATE INNER LOCK	Damaged	349.80 FL	*215.00 FL
14	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	198.70 FL	*198.70 FL
16	2		*TAILGATE HINGES	Not Necessary	136.00 FL	*- FL
17	2		*TAILGATE ABSORBERS	Not Necessary	397.20 FL	*- FL
18	1		*REAR WINDSCREEN MOULDING (1 SET)	Necessary	168.90 FL	*168.90 FL
19	1		*REAR WINDSCREEN INNNER SEAL	Necessary	60.00 FL	*60.00 FL
20	1		*REAR WINDSCREEN	Not Necessary	698.70 FL	*- FL
21	1		*REAR BUMPER	Deformed	978.20 FL	*745.00 FL
22	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	145.00 FL	*- FL
23	2		*REAR BUMPER ATTACHEMENT RETAINERS	Not Necessary	172.40 FL	*- FL
24	1		*REAR BUMPER CLIPS (1 SET)	Necessary	50.00 FL	*30.00 FL
25	1		*REAR BUMPER REFLECTORS	RH Cracked	197.20 FL	*98.60 FL
26	1		*REAR BUMPER UNDER COVER	Necessary	196.00 FL	*196.00 FL
27	1		*REAR BUMPER UNDER COVER CLIPS (1 SET)	Necessary	30.00 FL	*30.00 FL
28	1		*REAR CORNER BUMPER RH	RH Deformed	651.20 FL	*195.00 FL
29	1		*END PANEL	Dented	595.00 FL	*595.00 FL
30	1		*END PANEL TOP TRIM	Deformed	198.30 FL	*198.30 FL
31	1		*END PANEL TOP TRIM CLIPS (1 SET)	Necessary	30.00 FL	*20.00 FL
32	1		*SPARE TYRE PANEL	Repair	1,245.00 FL	*- FL
33	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	462.00 FL	*- FL
34	1		*SPARE TYRE PANEL TOP TOOL SPONGE	Torn	351.00 FL	*351.00 FL
35	1		*REAR KEY ANTENA SENSOR	Cracked	145.80 FL	*145.80 FL
36	1		*ALARM SENSOR BUZZER	Damaged	150.00 FL	*150.00 FL
37	1		*TAILLAMP	RH Cut	1,361.80 FL	*475.00 FL
38	1		*TAILLAMPS INNER SEALER	Not Necessary	40.00 FL	*- FL
39	1		*TAILLAMPS CLIPS (1 SET)	Not Necessary	30.00 FL	*- FL
40	1		*REAR FENDER INNER TRIM	RH Deformed	775.00 FL	*387.50 FL
41	1		*REAR FENDER INNER TRIM CLIPS (1 SET)	Necessary	60.00 FL	*30.00 FL
42	2		*REAR FENDER INNER COWLING	Not Necessary	374.40 FL	*- FL
43	1		*REAR FENDER INNER COWLING CLIP (2 SET)	Not Necessary	60.00 FL	*- FL
44	2		*REAR FENDER ARCH GARNISH	Not Necessary	416.60 FL	*- FL
45	2		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
46	1		*REAR EXHAUST SILENCER	Not Necessary	897.30 FL	*- FL
47	1		*REAR EXHAUST MOUNTING	Not Necessary	92.00 FL	*- FL
48	1		*REAR EXHAUST GASKET	Not Necessary	48.00 FL	*- FL
49	1		*REAR EXHAUST HEAT PLATE	Not Necessary	145.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
51	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
52	1		*REVERSE SENSOR (1 SET)	Damaged	250.00 FS	*200.00 FS
53	1		*REVERSE CAMERA (1 SET)	Not Necessary	380.00 FS	*- FS
54	1		*BODY PANEL JOINT SEALANT (1 SET)	Necessary	120.00 FS	*60.00 FS
55	1		*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,059.40	6,532.50
- List Item Discount on L Items 20.00/20.00% (\$)	3,209.88	1,242.50
Total Parts (\$)	13,849.52	5,290.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	700.00
2	SPRAY PAINTING	New	2,000.00	700.00
3	CHECK WIRING ON TAILLAMP	New	120.00	30.00
4	ANTI RUST	New	120.00	60.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	120.00	60.00
7	REMOVE AND INSTALL INTERIOR UPHOSLTERY	New	150.00	60.00
8	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	50.00
9	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
10	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			5,020.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >