



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBM 9967J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR MUDGUARD	CRACKED	\$110.00	\$110.00
1	REAR SIGNAL LIGHT	NOT NECESSARY	\$80.00	\$0.00
1	REAR PLATE NUMBER	BENT	\$50.00	\$30.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$14.00)
			\$240.00	\$126.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WORKMANSHIP		\$120.00	\$120.00
	LTA SEARCH		\$27.25	\$0.00
	ADMINISTRATIVE (PHONE CALLS/EMAILS/MESSAGES WITH THIRD PARTY INSURANCE COMPANY)		\$30.00	\$0.00
			\$177.25	\$120.00
GRAND TOTAL			\$417.25	\$246.00
RECOMMENDED COST OF REPAIRS				\$246.00
Report Ref No: CS/LIP24110477/Tqp3e2				

MARKET VALUE: \$7,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,789.00=NETT VALUE: \$4,711.00

**MTH**

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.