

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24110478/AMA3Q2  
**Date:** 11/04/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000154
<b>Claimant Vehicle No :</b>	JNA253	<b>Insured Vehicle No :</b>	SLT4580T
Date of Loss:	17/11/2024	Nature of Claim:	TP
		Claim No:	3062483780SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>JNA253</b>	Engine No:	1AZE017164
Make & Model:	TOYOTA CAMRY, 2.0 2.0 G (A)	Chassis No:	MR053BK4107004828
Reg. Date:	01/12/2008 (Man. Year: 2006)	Odometer:	81056 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,152.80	5,841.57	6,311.23	51.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	2,120.00	2,820.00	57.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,092.80</b>	<b>7,961.57</b>	<b>9,131.23</b>	<b>53.42</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,350.00</b>		
<b>(S\$)</b>	17,092.80	6,350.00	10,742.80	62.85
<b>+ GST 9.00/9.00% (S\$)</b>	1,538.35	571.50	966.85	62.85
<b>Nett Amount (S\$)</b>	<b>18,631.15</b>	<b>6,921.50</b>	<b>11,709.65</b>	<b>62.85</b>
<b>+ Loss of Use (9.0 x S\$40.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>7,308.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,300.00</b>		

**INSPECTION**

Date of Assignment:	19/11/2024	
Date Inspected:	19/11/2024 Inspected At:	HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	910.00 FL	*910.00 FL
2	1		*BOOTLID DETECTOR	Not Necessary	395.00 FL	*- FL
3	1		*BOOTLID LAMP	O/S Cut	840.00 FL	*420.00 FL
4	1		*BOOTLID EMBLEM CAMRY	Necessary	65.00 FL	*65.00 FL
5	1		*BOOTLID EMBLEM 2.0	Necessary	60.00 FL	*60.00 FL
6	1		*BOOTLID LOGO	Necessary	80.00 FL	*80.00 FL
7	2		*BOOTLID HINGE	Not Necessary	252.00 FL	*- FL
8	2		*BOOTLID STOPPER	Not Necessary	38.00 FL	*- FL
9	1		*BOOTLID INSULATOR	Not Necessary	265.00 FL	*- FL
10	1		*BOOTLID LOCK	Damaged	395.00 FL	*395.00 FL
11	1		*BOOTLID CATHER	Not Necessary	25.00 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Cut	240.00 FL	*240.00 FL
13	1		*REAR NUMBER PLATE GARNISH WITH MOULDING	Cracked	380.00 FL	*380.00 FL
14	1		*REAR BUMPER	Deformed	560.00 FL	*560.00 FL
15	2		*REAR BUMPER REFLECTOR	Not Necessary	150.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	140.00 FL	*- FL
17	2		*REAR BUMPER RETAINER (CORNER)	Not Necessary	160.00 FL	*- FL
18	2		*REAR BUMPER SCREW COVER GARNISH	Not Necessary	56.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	405.00 FL	*405.00 FL
20	1		*TAILLAMP	O/S Cut	1,070.00 FL	*535.00 FL
21	1		*TAILLAMP PANEL RH	Repair	230.00 FL	*- FL
22	2		*REAR FENDER INNER COWLING	Not Necessary	810.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	1,350.00 FL	*- FL
24	1		*REAR END PANEL	Dented	620.00 FL	*620.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	420.00 FL	*420.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Torn	280.00 FL	*280.00 FL
27	1		*REAR FLOOR PANEL	Buckled	1,140.00 FL	*1,140.00 FL
28	1		*REAR FLOOR SIDE PANEL RH	Not Necessary	586.20 FL	*- FL
29	1		*REAR SPARE TYRE BOLT	Not Necessary	32.00 FL	*- FL
30	1		*CENTER EXHAUST	Not Necessary	1,425.00 FL	*- FL
31	1		*CENTER EXHAUST INSULATOR	Not Necessary	170.00 FL	*- FL
32	1		*SET CENTER EXHAUST GASKET	Not Necessary	75.00 FL	*- FL
33	1		*REAR EXHAUST PIPE	Bent	892.10 FL	*892.10 FL
34	1		*REAR EXHAUST INSULATOR	Not Necessary	161.10 FL	*- FL
35	1		*SET REAR EXHAUST GASKET	Not Necessary	75.00 FL	*- FL
36	2		*REAR EXHAUST MOUNTING	Not Necessary	78.00 FL	*- FL
37	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
39	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
44	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
45	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>15,860.40</b>	<b>7,692.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	3,707.60	1,850.53
<b>Total Parts (\$)</b>	<b>12,152.80</b>	<b>5,841.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	160.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	REMOVE AND REFIX REAR EXHAUST	New	180.00	60.00
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	80.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,940.00</b>
				<b>2,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >