

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24110479/RVP3E2**Date:** 14/01/2025REFERENCE

Insured/Claimant:	ZHOU HAILONG	Policy No:	MPC23A00375400	Claim No:	DMPC2401589H/AF
Date of Loss:	19/11/2024	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF6998U	Engine No:	26492080016553
Make & Model:	MERCEDES-BENZ E300, 2.0 (A)	Chassis No:	WDD2130832A728568
Reg. Date:	17/12/2019 (Man. Year: 2019)	Odometer:	142934 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,328.60	7,347.80	4,980.80	40.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,180.00	350.00	22.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,858.60	8,527.80	5,330.80	38.47
Approved Total (Overridden) (S\$)		6,800.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	13,858.60	6,050.00	7,808.60	56.34
+ GST 9.00/9.00% (S\$)	1,247.27	544.50	702.77	56.34
Nett Amount (S\$)	15,105.87	6,594.50	8,511.37	56.34

INSPECTION

Date of Assignment:	21/11/2024	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	26/11/2024	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2025)
Parts:	M1-COUPE	MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF6998U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE (WCP)	Bent	35.00 FS	*35.00 FS
2	1		*FRT NUMBER PLATE HOLDER (WCP)	Deformed	105.00 F	*105.00 F
3	1		*FRT BUMPER (WCP)	Deformed	1,175.00 F	*1,175.00 F
4	2		*FRT BUMPER RETAINER LH/RH (WCP)	Serviceable	20.00 F	*- F
5	1		*FRT BUMPER LOWER CENTER CARRIAGE (WCP)	Serviceable	118.00 F	*- F
6	1		*FRT BUMPER LWR CENTER TRIM (WCP)	Serviceable	95.00 F	*- F
7	1		*FRT BUMPER SPONGE (WCP)	Serviceable	150.00 F	*- F
8	1		*FRT GRILLE ASSY (WCP)	Cracked	165.00 F	*165.00 F
9	1		*FRT GRILLE OUTER CENTER MOULDING (WCP)	Necessary	225.00 F	*225.00 F
10	4		*FRT GRILLE OUTER CENTER TRIM (WCP)	Cracked	260.00 F	*260.00 F
11	1		*FRT GRILLE OUTER TRIM (WCP)	Necessary	210.00 F	*210.00 F
12	1		*FRT GRILLE EMBLEM (WCP)	Necessary	105.00 F	*105.00 F
13	1		*FRT GRILLE EMBLEM BASE (WCP)	Cracked	78.00 F	*78.00 F
14	1		*FRT CAMERA (WCP)	Serviceable	1,150.00 F	*- F
15	1		*FRT CAMERA CAP (WCP)	Serviceable	10.00 F	*- F
16	2		*FRT PARKING AID SENSOR CENTER LH/RH (WCP)	Serviceable	270.00 F	*- F
17	1		*FRT BONNET (WCP)	Bent	1,645.00 F	*1,645.00 F
18	1		*FRT BONNET EMBLME (WCP)	Necessary	60.00 F	*60.00 F
19	1		*FRT HEADLAMP LH/RH (WCP)	O/S NotNecessary / N/S Cracked	4,700.00 F	*2,350.00 F
20	2		*FRT HEADLAMP LOWER BRACKET LH/RH (WCP)	Serviceable	260.00 F	*- F
21	1		*FRT BUMPER LOWER CENTER GARNISH (WCP)	Serviceable	105.00 F	*- F
Supplementary #1						
22	1		*FRT UPPER RADIATOR SUPPORT PANEL (WCP)	Cracked	190.00 F	*190.00 F
23	1		*FRT BONNET OPENER (WCP)	Bent	80.00 F	*80.00 F

F=Franchise part. S=SpcNett.

	Sub Total (S\$)	11,211.00	6,683.00
	+ Margin on L,N Items 10.00/10.00% (S\$)	1,117.60	664.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						12,328.60
						7,347.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, WELD,REMOVE & REPLACE ABOVE PARTS	New	600.00	550.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New	280.00	200.00
Gross Labour Cost (\$\$)			1,530.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >