



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHD 648R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER COVER REAR	TORN	\$561.70	\$561.70
1	BUMPER BRACKET CTR REAR	SERVICEABLE	\$98.10	\$0.00
1	BUMPER BRACKET SIDE RH REAR	CRACKED	\$82.10	\$82.10
1	BUMPER RETAINER LH REAR	SERVICEABLE	\$54.20	\$0.00
1	BUMPER RETAINER RH REAR	CRACKED	\$59.80	\$59.80
1	BUMPER LOWER REAR	CRACKED	\$411.90	\$411.90
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	\$547.80	\$0.00
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	\$114.50	\$0.00
1	BUMPER REFLECTOR RH	BROKEN	\$16.60	\$16.60
1	BOOT REFLECTOR LAMP RH	CRACKED	\$277.70	\$277.70
1	TAILLAMP RH	BROKEN	\$401.40	\$401.40
1	FENDER PANEL REAR RH	BENT	\$1,933.20	\$1,933.20
1	WHEELARCH REAR RH	CRACKED	\$275.40	\$275.40
1	OUTER PANEL REAR (END PANEL)	BENT	\$745.80	\$745.80
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	\$404.56	\$404.56
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	\$1,229.40	\$0.00
1	BOOT REAR	BENT	\$1,677.20	\$1,677.20
1	BOOT FINISHER	SERVICEABLE	\$344.70	\$0.00
1	BOOT LOCK	TO REPAIR SEE LABOUR	\$246.60	\$0.00
1	BOOT WEATHERSTRIP	SERVICEABLE	\$178.20	\$0.00
1	BOOT STRUT LH	SERVICEABLE	\$145.10	\$0.00
1	BOOT STRUT RH	SERVICEABLE	\$145.10	\$0.00
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	\$254.20	\$0.00
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	\$254.20	\$0.00
1	BOOT BADGE 'RENAULT'	NECESSARY	\$82.40	\$82.40
1	BOOT BADGE	NECESSARY	\$95.80	\$95.80
	LESS 10.00% DISCOUNT		(\$1,063.77)	(\$702.56)
			\$9,573.89	\$6,323.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET PARKING AID (SN)	TORN	\$700.00	\$400.00
1	REAR BUMPER CLIP (SN)	NECESSARY	\$65.00	\$65.00
1	REAR LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
1	REAR RH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
1	REAR TAIL LAMP CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
1	END PANEL INNER TRIM CLIP (SN)	NECESSARY	\$60.00	\$60.00
1	REAR BUMPER PROTECTOR (SN)	NO SUCH PARTS	\$180.00	\$0.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	\$150.00	\$40.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	\$200.00	\$0.00
1	WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	\$130.00	\$30.00
1	TYRE (\$280.00) (70%) (SN)	PUNCTURE	\$350.00	\$196.00
1	RIM (SN)	BENT	\$300.00	\$300.00
			\$2,330.00	\$1,091.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS		\$600.00	\$90.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$2,000.00	\$1,100.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET RH REAR, SPARE WHEEL PANEL, BOOT LOCK, BOOT HINGE LH AND BOOT HINGE RH		\$2,000.00	\$1,200.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST		\$170.00	\$60.00
	TO REMOVE AND REFIT INETRIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR		\$380.00	\$100.00
	TO REINSTALL REAR BUMPER PARKING SENSOR		\$170.00	\$60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT		\$220.00	\$60.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	REPEATED	\$170.00	\$0.00
			\$5,710.00	\$2,670.00

GRAND TOTAL			\$17,613.89	\$10,084.00
--------------------	--	--	--------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF REPAIRS		\$10,084.00
Report Ref No: CS/AGI24110482/Kvp3m4			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.