



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cycle & Carriage Kia Pte Ltd 239 Alexandra Road Singapore 159930 Contact No	Cust No/Name	/Cycle & Carriage Kia Pte Ltd
	Reg No/Reg Date	SNH6075L / 24/08/2021
	Date In/Mileage	21/11/2024/ 21121
	Chassis No	KNAF5416MN5115867
	Engine No	G4FGMH707927
	Make/Model	KIA/CERATO 1.6 A GT LINE H439 PE
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	21/11/2024/ 17:48	REN	979 / Renemer Ramirez Bag	36950

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT ACCIDENT ON 21/11/2024 ALONG TAMPINES AVENUE 10 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP#: SNH8552M TP INS: ECICS				
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE				280.00
A 90000001 TO CHECK WIRING AND ELECTRICAL SYSTEM				100.00
E PNT88000 TO TRANSFER TRUNK LID COMPONENTS & MECHANISM				640.00
E PNT88000 TO REMOVE & RE-INSTALL FLOOR BOARDS, CARPETS & TRIMS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	320			640.00
E PNT88000 TO REPLACE LOGO, EMBLEM, TRUNK LID, UPR & LWR REAR BUMPER, CLIPS, SIDE BRACKETS, LH/RH T/SIGNAL LAMP & COVER, EXTN WIRING, ANTENNA, BEAM & BRACKETS, LH/RH STAY, LH UNDER COVER, ETC -TO REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	1920			2560.00
E PNT98000 SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS (TRUNK LID, UPR REAR BUMPER, REAR END PANEL)	1650			2200.00
E PNT88000 TO CHECK, TEST & REFIT REVERSE SENSOR				100.00
M SUNDRY TO APPLY BODY SEALANT ON NEW PANELS				200.00
M SUNDRY TO APPLY ANTI-CORROSION ON AFFECTED AREAS				200.00
M SUNDRY SUNDRIES			nec	50.00
M EMBLEM-KIA	1.00	38.00	00.00	38.00
M EMBLEM-CERATO	1.00	28.00	00.00	28.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cycle & Carriage Kia Pte Ltd	Cust No/Name	/Cycle & Carriage Kia Pte Ltd
239 Alexandra Road	Reg No/Reg Date	SNH6075L / 24/08/2021
Singapore 159930	Date In/Mileage	21/11/2024/ 21121
Contact No	Chassis No	KNAF5416MN5115867
	Engine No	G4FGMH707927
	Make/Model	KIA/CERATO 1.6 A GT LINE H439 PE
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	21/11/2024/ 17:48	REN	979 / Renemer Ramirez Bag	36950

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-GT LINE / RC	1.00	45.00	00.00	45.00
M PANEL ASSY-TRUNK LID / RC	1.00	1810.00	00.00	1810.00
M COVER-RR BUMPER / RC	1.00	749.00	00.00	749.00
M COVER-RR BUMPER LWR / RC	1.00	232.00	00.00	232.00
M CLIP-BUMPER / RC	10.00	1.00	00.00	10.00
M BRACKET ASSY-RR BPR SIDE UPR,LH / RC	1.00	31.00	00.00	31.00
M BRACKET-ASSY RR BPR SIDE UPR,RH / nn	1.00	26.00	00.00	26.00
M COVER-RR BUMPER FOG LAMP,LH / nn	1.00	39.00	00.00	39.00
M COVER-RR BUMPER FOG LAMP,RH / nn	1.00	39.00	00.00	39.00
M LAMP ASSY-SIDE T/SIGNAL,LH / nn	1.00	201.00	00.00	201.00
M LAMP ASSY-SIDE T/SIGNAL,RH / nn	1.00	201.00	00.00	201.00
M ULTRASONIC SENSOR ASSY-BWS / nn	1.00	163.00	00.00	163.00
M EXTN WIRING ASSY-BWS / nn	1.00	207.00	00.00	207.00
M ANTENNA ASSY-SMARTKEY / nn	1.00	46.00	00.00	46.00
M BRACKET-RR BPR UPR MTG / nn	2.00	42.00	00.00	84.00
M BRACKET-RR BEAM LWR,CTR / nn	1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR MTG / nn	2.00	7.00	00.00	14.00
M BEAM-RR BUMPER / nn	1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH / nn	1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH / nn	1.00	65.00	00.00	65.00
M COVER-RR BUMPER UNDER,LH / nn	1.00	33.00	00.00	33.00

STEVE CLKK
 26/11/24, 10:30am
 W K
 PIP
 by Bel my

Confirm & accepted by

6 -4 days

	Nett	11,909.00
9% GST on	11909.00	1071.81
Total Payable		12,980.81

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

This is a computer generated document, no signature is required. The above estimate is based on our initial inspection and does not include any work that has commenced. Occasionally worn or damaged parts are discovered however, should this occur, we would advise you. Please be informed that a deposit of the work. Payment for this may be made in cash, credit card or the windscreen in the event of inadvertent breakage in the course of renewing the windscreen.