

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24110489/KQP3M4**Date:** 15/04/2025REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00610
Claimant Vehicle No :	SMR1507A	Insured Vehicle No :	SNH7925C
Date of Loss:	13/11/2024	Nature of Claim:	TP
		Claim No:	M2406698

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1507A		
Make & Model:	TOYOTA VELLFIRE HYBRID, 2.5 7-SEATER Z CVT (A)	Engine No:	2AR2250910
Reg. Date:	20/12/2019 (Man. Year: 2019)	Chassis No:	AYH300092403
Colour:	Black	Odometer:	127063 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 ZR18	Rear Tyre Size:	235/50 ZR18
Front Left Side:	RAPID 5 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	RAPID 5 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,852.50	3,919.50	3,933.00	50.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	440.00	610.00	58.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,902.50	4,359.50	4,543.00	51.03
+ GST 9.00/9.00% (S\$)	801.23	392.36	408.87	51.03
Nett Amount (S\$)	9,703.73	4,751.86	4,951.87	51.03

INSPECTION

Date of Assignment:	22/11/2024	
Date Inspected:	25/11/2024	Inspected At: COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD SINGAPORE 579701
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,718.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2025)
Parts:	M1-MPV	TOYOTA VELLFIRE HYBRID 2.5 7-SEATER Z CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR1507A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RADIATOR GRILLE	* Check	2,300.00 FL	*- FL
2	1		*FRT BUMPER CENTRE	Repair	1,350.00 FL	*- FL
3	1		*FRT BUMPER LOWER (NO.2) (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*FRT CENTRE CHROME	Dented/Cut	355.00 FL	*355.00 FL
5	2		*FRT LH CHROME	Scratched	180.00 FL	*180.00 FL
6	1		*FRT LOWER HL	Cut	3,820.00 FL	*3,820.00 FL
7	1		*FRT LH CORNER PANEL WITH CHROME	* Check	720.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					8,725.00	4,355.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					872.50	435.50
Total Parts (\$\$)					7,852.50	3,919.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, REMOVE REFIT NECESSARY	New	500.00	200.00
2	TO PUTTY SPRAY PAINT NECESSARY	New	500.00	220.00
3	HL WIRING	New	50.00	20.00
Gross Labour Cost (\$\$)			1,050.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >