



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMH 8365Z

| REPLACEMENT OF PARTS |                            |                      |                        |                   |
|----------------------|----------------------------|----------------------|------------------------|-------------------|
| Qty                  | Description of Parts       | Condition            | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                    | REAR BUMPER                | TO REPAIR SEE LABOUR | \$1,422.00             | \$0.00            |
| 1                    | REAR BUMPER LOWER DIFFUSER | TO REPAIR SEE LABOUR | \$850.00               | \$0.00            |
| 2                    | REAR BUMPER RETAINER       | NOT NECESSARY        | \$110.00               | \$0.00            |
| 1                    | SET REAR BUMPER CLIP       | NOT NECESSARY        | \$65.00                | \$0.00            |
| 1                    | REAR REVERSE SENSOR        | NOT NECESSARY        | \$400.00               | \$0.00            |
| 1                    | REAR EXHAUST PIPE          | NOT NECESSARY        | \$600.00               | \$0.00            |
| 1                    | JOINT SEALANT              | NOT NECESSARY        | \$120.00               | \$0.00            |
|                      |                            |                      | \$3,567.00             | \$0.00            |

| Labour |  |               |                        |                   |
|--------|--|---------------|------------------------|-------------------|
|        | Description of Parts   | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
|        | CHECK REAR WIRING AND LIGHTNING SYSTEM   | NOT NECESSARY | \$150.00               | \$0.00            |
|        | REMOVE AND REFIX REAR REVERSE SENSOR   |               | \$150.00               | \$20.00           |
|        | REMOVE AND STRAIGHTEN REAR EXHAUST   | NOT NECESSARY | \$150.00               | \$0.00            |
|        | PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER DIFFUSER |               | \$400.00               | \$180.00          |
|        | SPRAY PAINTING ON AFFECTED AREAS   |               | \$600.00               | \$400.00          |
|        | APPLY ANTI-RUST ON AFFECTED AREAS  | NOT NECESSARY | \$150.00               | \$0.00            |
|        |  |               | \$1,600.00             | \$600.00          |

|                                    |                             |            |          |
|------------------------------------|-----------------------------|------------|----------|
| GRAND TOTAL                        |                             | \$5,167.00 | \$600.00 |
|                                    | RECOMMENDED COST OF REPAIRS |            | \$600.00 |
| Report Ref No: CS/AGI24060293/Uqh3 |                             |            |          |

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.