

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110501/RPA3Q2  
Date: 27/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_05  
Claimant Vehicle No : SLQ3820Z Insured Vehicle No : GBK1525P  
Date of Loss: 18/11/2024 Nature of Claim: TP Claim No: MFL2024D0013853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ3820Z  
Make & Model: HYUNDAI AE IONIQ HEV DCT SR, 1.6 (A) Engine No: G4LEHU438469  
Reg. Date: 07/07/2017 (Man. Year: 2017) Chassis No: KMHC851CVHU044525  
Colour: White Odometer: 70026 km  
Engine Capacity: 1580 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,620.80	2,106.40	1,514.40	41.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,750.00	2,270.00	3,480.00	60.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,370.80</b>	<b>4,376.40</b>	<b>4,994.40</b>	<b>53.30</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>843.37</b>	<b>393.88</b>	<b>449.49</b>	<b>53.30</b>
<b>Nett Amount (S\$)</b>	<b>10,214.17</b>	<b>4,770.28</b>	<b>5,443.89</b>	<b>53.30</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>5,012.46</b>		

INSPECTION

Date of Assignment: 27/11/2024  
Date Inspected: 27/11/2024 Inspected At: Komoco Motors Pte Ltd (HQ)  
253 ALEXANDRA ROAD, #01-01  
Singapore 159936  
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Jan 2025)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT SR 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3820Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CAP ASSY WHEEL HUB	Not Necessary	123.00 FL	*- FL
2	1		*VALVE-TPMS	Not Necessary	142.00 FL	*- FL
3	1		*COVER FR BUMPER	Torn	515.00 FL	*515.00 FL
4	1		*DUCT ASSY AIR CURTAIN RH	Cracked	14.00 FL	*14.00 FL
5	1		*BRACKET FR BUMPER SIDE SUPT RH	Not Necessary	12.00 FL	*- FL
6	1		*BRACKET FR BUMPER SIDE RH	Cracked	20.00 FL	*20.00 FL
7	1		*LAMP ASSY ,HEAD RH	Scratched	1,199.00 FL	*1,199.00 FL
8	1		*MOULDING FRONT BUMPER CTR UPR	Scratched	142.00 FL	*142.00 FL
9	1		*LAMP ASSY DAY RUNNING LIGHT RH	Cracked	643.00 FL	*643.00 FL
10	1		*MOULDING FRONT BUMPER RH	Cracked	55.00 FL	*55.00 FL
11	10		*FRT BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
12	1		*WHEEL ASSY ALUMINIUM	Not Necessary	1,591.00 FL	*- FL
13	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,516.00	2,628.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					895.20	521.60
Total Parts (\$\$)					3,620.80	2,106.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT ACCIDENT BODY REPAIR -FRT RH FENDER /FRT BUMPER	New	1,840.00	920.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT BUMPER /FRT BUMPER MOULDING RH/FRT BUMPER GARNISH /FRT FENDER RHS	New	1,900.00	950.00
3	TO REALIGN FRT HEADLAMP	New	40.00	40.00
4	TO REPROGRAMME AFTER ACCIDENT REPAIR	New	180.00	180.00
5	TO CHECK ELECTRICAL SYSTEM AFTER ACCIDENT REPAIR	New	180.00	180.00
6	TO PERFORM 4 WHEEL ALIGNMENT	New	150.00	0.00
7	TO REPAIR REAR INNER FENDER RHS	New	460.00	0.00
8	TO RENEW FRT WHEEL	New	80.00	0.00
9	TO R&I EV BATTERY TO FACILITATE REPAIR	New	920.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,750.00</b>	<b>2,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >