

(GST REGISTRATION NO: MR-8500364-4)

Date : 23/11/2024

India International Insurance Pte Ltd
Attn: Motor Claims Department

Vehicle number

Make and model

Registration Date

Chassis number

Engine number

: SLQ3820Z

: IONIQ 1.6 5DR DCT S/R HYBRID

: 11/06/2024

: KMHC851CVHU044525

: G4LEHU438469

Claim Officer

Job No.

Owner name

Date of Acc

Policy number

Claim Type

: Robyn

:

: ALEX KOH BOON

: 18/11/2024

: A 300633021 AH1

: TP

FRT Items :			2nd	Estimate	Revised
1	CAP ASSY-WHEEL HUB	52960G2100		\$ 123.00	
2	VALVE-TPMS	52933D4100		\$ 142.00	
3	COVER-FR BUMPER	86510G2000		\$ 515.00	
4	DUCT ASSY-AIR CURTAIN,RH	86568G2000		\$ 14.00	
5	BRACKET-FR BUMPER SIDE SUPT,RH	86556G2000		\$ 12.00	
6	BRACKET-FR BUMPER SIDE,RH	86514G2000		\$ 20.00	
7	LAMP ASSY-HEAD,RH	92102G2040MBL		\$ 1,199.00	
8	MOULDING-FRONT BUMPER CTR,UPR	86585G2000		\$ 142.00	
9	LAMP ASSY-DAY RUNNING LIGHT,RH	92208G2000		\$ 643.00	
10	MOULDING-FRONT BUMPER,RH	86564G2050		\$ 55.00	
11	FRT BUMPER CLIP X10	865952T500		\$ 20.00	
12	WHEEL ASSY-ALUMINIUM	52905G2300		\$ 1,591.00	
				\$ 4,476.00	
Less 25% Discount				\$ 1,119.00	
Material total				\$ 3,357.00	

Vehicle number **SLQ3820Z**

Body,Paint & Labour Items :		Estimate
1	To carry out accident body repair - FRT RH FENDER / FRT BUMPER (\$460)	\$ 1,840.00
2	Complete putty and spray paint all affected areas - FRT BUMPER / FRT BUMPER MOULDING RH/ FRT BUMPER GARNISH / FRT FENDER RHS (\$380)	\$ 1,900.00

Labour Charges:	2nd	Estimate	Revised
3 TO REALIGN FRT HEADLAMP (S.NETT)	\$	40.00	
4 TO REPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00	
5 TO CHECK ELECTRICAL SYSTEM AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00	
6 SUNDRIES (S.NETT)	\$	40.00	
7 TO PERFORM 4 WHEEL ALIGNMENT (S.NETT)	\$	150.00	
9 TO REPAIR REAR INNER FENDER RHS (S.NETT)	\$	460.00	
16 TO RENEW FRT WHEEL (S.NETT)	\$	80.00	
17 TO R&I EV BATTERY TO FACILITATE REPAIR (S.NETT)	\$	920.00	
Total Labour	\$	5,790.00	
Total Parts	\$	3,357.00	
Excess	\$	-	
	\$	9,147.00	
Add GST 9%	\$	823.23	\$ -
Grand Total	\$	9,970.23	\$ -

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***