

ASS. REC. BY:

REF:

C9/MSG 24110502/Kap3

C

Kenneth

ASSIGNMENT

Snp

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Eek 5025X

Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy Voxy

c.c. 1797

Colour _____

M. P. White

A/C: Insured / Std / NI / NA

Sp. Reading _____

97038

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

EWR 90

0116575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

21/11/24

D.O.I. _____

25/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 En not ready

01/12 04909.98 Cabul

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

5

Resurvey No. of Trip: _____

2

Survey Fee: _____

Transportation

S + RS. SI

Fuel

Others

Add Fee: _____

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

ESTIMATE RC AUTO

Not Notified
Repairing BY paint
B 4909.98

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

5 days

SNP 5025 X

Date : 04.12.2024

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOTLID 1985.90	By	2773	70
1 PC	REAR BUMPER	Bar	1092	80
1 PC	REAR LAMP LOWER COVER	mi	90	00
1 PC	REAR LEFT HAND REFLECTOR	CR	165	10
1 PC	REAR END PANEL ASSY 945.50	B	1134	50
4 PCS	REAR BUMPER SIDE CLIP@3.50	m	14	00
2 PCS	REAR BUMPER U SONIC RETAINER @55.20	nn	110	40
		TOTAL	5380	10
		LESS 25	4035	07
	TO RESPRAY AFFECTED PORTION		700	00
	TO REINSTATE REAR WINDSCREEN		180	00
	TO RENEW ABOVE PARTS		1200	00
	ANTI RUST		60	00
	TO TRANSFER REAR TAILGATE ACCESSORIES		80	00
	TO CHECK WIRING		50	00
	TO REMOVE REAR RADIO WOOFER AND SPEAKERS		250	00
	TO REATTACHED SOUND PROOF		300	00
	GRAND TOTAL		6855	07

✓
✓
✓
✓
✓
✓
X

6001
1201
6001
✓
601
201
801
1501

Received the above goods in good order and condition

for RC AUTO

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorised Signature