



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 510H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	GRAZED	\$810.60	\$731.20
2	FRONT BUMPER SIDE RETAINER L/R	NOT NECESSARY	\$296.80	\$0.00
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	\$436.10	\$0.00
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	\$131.00	\$0.00
1	HEADLAMP RH	NOT NECESSARY	\$2,436.20	\$0.00
1	HEADLAMP TOP PANEL GARNISH RH	NOT NECESSARY	\$312.30	\$0.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	\$2,068.10	\$0.00
1	FRONT DOOR WINDOW OUTER MOULDING RH	NOT NECESSARY	\$279.40	\$0.00
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	\$288.10	\$0.00
1	FRONT STEP PANEL GARNISH RH	NOT NECESSARY	\$211.70	\$0.00
1	FRONT STEP PANEL RH	NOT NECESSARY	\$371.20	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$1,910.38)	(\$182.80)
			\$5,731.12	\$548.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIPS (SN)	NECESSARY	\$60.00	\$30.00
1	FRONT BUMPER LOWER LIP (SN)	GRAZED	\$900.00	\$600.00
1	HEADLAMP TOP PANEL GARNISH RH CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	FRONT DOOR TRIMBOARD LH CLIPS (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT STEP PANEL GARNISH LH CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
			\$1,080.00	\$630.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT WIRING & HEADLAMP LEVELING		\$60.00	\$20.00
	TO REMOVE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR	NOT NECESSARY	\$120.00	\$0.00
	TO CONDUCT WHEEL ALIGNMENT	NOT NECESSARY	\$120.00	\$0.00
	TO PROVIDE LABOUR, WORKMANSHIP. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH		\$1,000.00	\$300.00
	TO SPRAY PAINT ON AFFECTED PANELS		\$800.00	\$300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	RUST PROOFING	NOT NECESSARY	\$60.00	\$0.00
			\$2,160.00	\$620.00
GRAND TOTAL			\$8,971.12	\$1,798.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,400.00
Report Ref No: CS/FCI24110506/Uvp3m4				

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.