



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110506/Uvp3m4
16 RAFFLES QUAY	Date:	03/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7804B	Veh. Inspected	GBL 510H
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010264MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	25/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE DX 2.8 AUTO	C.C	2754
Engine No.	1GD8662242	Year of Reg.	26/02/2021
Chassis No.	GDH2012016344	Colour	BLUE
Odometer	115064 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	AGILIS	6
L/H Front Tyre	195R15	AGILIS	6
R/H Rear Tyre	195R15	AGILIS	6
L/H Rear Tyre	195R15	AGILIS	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	22/11/2024	Inspection Date	25/11/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days