

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110508/EMA3Q2**Date:** 11/03/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070171978
Claimant Vehicle No :	SNF6639X	Insured Vehicle No :	SGC2388U
Date of Loss:	25/11/2024	Nature of Claim:	TP
		Claim No:	6775645945SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF6639X		
Make & Model:	AUDI A6, 2.0 DESIGN TFSI (140 KW) (A)	Engine No:	DKY015447
Reg. Date:	14/06/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF21MN075807
Colour:	White	Odometer:	31458 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,885.00	3,776.00	6,109.00	61.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,152.00	1,702.00	1,450.00	46.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,037.00	5,478.00	7,559.00	57.98
+ GST 9.00/9.00% (S\$)	1,173.33	493.02	680.31	57.98
Nett Amount (S\$)	14,210.33	5,971.02	8,239.31	57.98
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,273.20		

INSPECTION

Date of Assignment:	28/11/2024		
Date Inspected:	28/11/2024	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	3,397.00 FS	*2,717.60 FS
2	1		*REAR BUMPER SPOILER	Cut	1,107.00 FS	*885.60 FS
3	2		*REAR BUMPER CHROME TRIM -LH/RH	Not Necessary	614.00 FS	*- FS
4	1		*REAR BUMPER CHROME TRIM CENTER	Not Necessary	215.00 FS	*- FS
5	1		*REAR BUMPER SECURING STRIP	Necessary	216.00 FS	*172.80 FS
6	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	554.00 FS	*- FS
7	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	244.00 FS	*- FS
8	1		*REAR AERIAL KEY ACCESS	Not Necessary	129.00 FS	*- FS
9	2		*REAR TELEPHONE AERIAL -LH/RH	Not Necessary	197.00 FS	*- FS
10	2		*REAR BUMPER REFLECTOR -LH/RH OUTER	Not Necessary	98.00 FS	*- FS
11	2		*REAR BUMPER REFLECTOR -LH/RH INNER	Not Necessary	82.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR -INNER/OUTER	Not Necessary	629.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
14	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,232.00 FS	*- FS
15	2		*REAR BUMPER SEAL LH/RH	Not Necessary	36.00 FS	*- FS
16	1		*REAR BUMPER HOLDING STRAP -CENTER	Not Necessary	149.00 FS	*- FS
17	1		*REAR BUMPER GUIDE SECTION -CENTER	Not Necessary	133.00 FS	*- FS
18	2		*REAR BUMPER GUIDE PROFILE LH/RH	Not Necessary	168.00 FS	*- FS
19	2		*REAR BUMPER GUIDE SECTION -LH/RH UPPER	Not Necessary	114.00 FS	*- FS
20	2		*REAR BUMPER GUIDE SECTION -LH/RH LOWER	Not Necessary	160.00 FS	*- FS
21	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,885.00	3,776.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ,TO REPAIR REAR END PANELLING RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,000.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	1,500.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			3,152.00	1,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >