

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110510/AMA3Q2**Date:** 17/03/2025**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414_05
Claimant Vehicle No :	SJS1273D	Insured Vehicle No :	SNH849K
Date of Loss:	22/11/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS1273D	Engine No:	2AZ1B09223
Make & Model:	TOYOTA PREVIA AERAS, 2.4 CVT MR (A)	Chassis No:	JTEGD56M307172486
Reg. Date:	28/06/2019 (Man. Year: 2019)	Odometer:	72987 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,904.95	5,764.00	5,140.95	47.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	2,090.00	1,040.00	33.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,034.95	7,854.00	6,180.95	44.04
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	14,034.95	6,250.00	7,784.95	55.47
+ GST 9.00/9.00% (S\$)	1,263.15	562.50	700.65	55.47
Nett Amount (S\$)	15,298.10	6,812.50	8,485.60	55.47
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,414.68		
Global Sum Settlement (S\$)		7,400.00		

INSPECTION

Date of Assignment:	03/12/2024		
Date Inspected:	03/12/2024	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2025)
Parts:	M1-MPV	TOYOTA PREVIA AERAS 2.4 CVT MR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS1273D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	917.90 FL	*917.90 FL
2	2		*REAR BUMPER SIDE HOLDER LH & RH	Not Necessary	120.40 FL	*- FL
3	2		*REAR BUMPER TOW COVER	Not Necessary	56.20 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LH & RH	N/S Cracked	121.60 FL	*60.60 FL
5	2		*REAR BUMPER SENSOR	Damaged	710.80 FL	*710.80 FL
6	2		*REAR BUMPER SENSOR HOLDER	Necessary	50.20 FL	*50.20 FL
7	1		*REAR END PANEL	Dented	1,151.30 FL	*1,151.30 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	336.80 FL	*336.80 FL
9	1		*REAR END PANEL LOWER GARNISH	Deformed	259.80 FL	*259.80 FL
10	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	200.60 FL	*- FL
11	2		*TAIL LAMP LH & RH	Not Necessary	1,508.20 FL	*- FL
12	1		*TAILGATE	Dented	2,671.70 FL	*2,671.70 FL
13	1		*TAILGATE LOCK	Damaged	495.50 FL	*495.50 FL
14	1		*TAILGATE WEATHERSTRIPE	Damaged	397.40 FL	*397.40 FL
15	1		*TAILGATE INNER TRIM BOARD	Not Necessary	694.50 FL	*- FL
16	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	312.40 FL	*- FL
17	1		*TAILGATE GLASS MOULDING	Necessary	185.90 FL	*185.90 FL
18	1		*TOYOTA LOGO	Necessary	75.80 FL	*75.80 FL
19	1		*TOYOTA WORDING	Necessary	60.40 FL	*60.40 FL
20	1		*PREVIA WORDING	Necessary	57.90 FL	*57.90 FL
21	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	1,266.90 FL	*- FL
22	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	2,514.40 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*REAR END PANEL TOP GARNISH CLIPS (1 SET)	Necessary	20.00 FS	*20.00 FS
25	1		*SET REAR END PANEL LOWER GARNISH CLISP	Necessary	20.00 FS	*20.00 FS
26	1		*SET REAR END PANE SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
29	2		*SETS REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,446.60	7,622.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,541.65	1,858.00
Total Parts (\$\$)	10,904.95	5,764.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO CHECK WIRING	New	50.00	0.00
5	TO APPLY TUFF COAT	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO REMOVE UPHOLSTERY	New	150.00	80.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			3,130.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >