5/2/25, 2:19 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060295/RUA3Q2

Date: 02/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MCV0007117_01

Claimant Vehicle GBH5524G Insured Vehicle No: YQ7387C

No:

Date of Loss: 25/05/2024 Nature of Claim: TP Claim No: MCV2024D0006645

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH5524G**

MITSUBISHI L200, 2.4 D DOUBLE CAB (A) Make & Model: Engine No: 4N15UCA0948

Reg. Date: 09/07/2018 (Man. Year: 2017) Chassis No: MMCJYKL10HH024999

Colour: White Odometer: 94211 km

Engine Capacity: 2442 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 245/70 R16 Rear Tyre Size: 245/70 R16 Front Left Side: Rear Left Side: Firenza 7 mm Firenza 7 mm Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,069.00	5,784.00	2,285.00	28.32
Miscellaneous Items		0.00	0.00	0.00	
Labour		12,020.00	7,390.00	4,630.00	38.52
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	20,089.00	13,174.00	6,915.00	34.42
	+ GST 9.00/9.00% (S\$)	1,808.01	1,185.66	622.35	34.42
	Nett Amount (S\$)	21,897.01	14,359.66	7,537.35	34.42

+ Car Rental (8.0 x S\$135.00/day + 9.00% GST) (S\$) 1,177.20

+ Doc/Search Fee (S\$) 2.18

15,539.04 **Nett Liability (S\$)**

15,500.00 Global Sum Settlement (S\$)

INSPECTION

Date Inspected:

Date of Assignment: 10/07/2024

Cycle & Carriage Automotive Pte Ltd (Pandan

Gardens) 10/07/2024 Inspected At:

209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 6.0 days

MOHD RASUL Manager: NA MENG YAN Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/2/25, 2:19 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Feb 2025)

Parts: N/A MITSUBISHI L200 2.4 D DOUBLE CAB (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH5524G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Par	t No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH CASING	Necessary	85.00 FS	*85.00 FS
2	1		*C&C EMBLEM	Necessary	50.00 FS	*50.00 FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
4	1		*FACE RR BUMPER	Bent	1,074.00 FS	*1,074.00 FS
5	1		*COVER ,RR BUMPER	Serviceable	45.00 FS	*- FS
6	1		*COVER ,RR BUMPER LH	Serviceable	35.00 FS	*- FS
7	1		*COVER ,RR BUMPER RH	Serviceable	35.00 FS	*- FS
8	1		*REINFORCEMENT RR BUMPER	Serviceable	703.00 FS	*- FS
9	1		*GATE ,RR BODY RR	Bent	1,301.00 FS	*1,301.00 FS
10	1		*MARK THREE-DIA	Necessary	74.00 FS	*74.00 FS
11	1		*MARK DIESEL	Necessary	31.00 FS	*31.00 FS
12	1		*DECAL COMMON RAIL	Necessary	4.00 FS	*4.00 FS
13	1		*MARK L200	Necessary	31.00 FS	*31.00 FS
14	1		*MARK MITSUBISHI	Necessary	66.00 FS	*66.00 FS
15	1		*SILL RR BODY FLOOR RR END	Serviceable	439.00 FS	*- FS
16	1		*SILL RR BODY FRAME	Serviceable	350.00 FS	*- FS
17	1		*GATE ,RR BODY SIDE LH	Buckled	1,182.00 FS	*1,182.00 FS
18	1		*PNL R/BODY SIDE SKRT RR LH	Serviceable	128.00 FS	*- FS
19	1		*LAMP ASSY ,COMB RR LH	Cracked	488.00 FS	*488.00 FS
20	1		*LAMP ASSY ,COMB RR RH	Not Necessary	488.00 FS	*-FS
21	1		*LAMP ASSY ,LICENSE PLATE	Serviceable	32.00 FS	*- FS
22	1		*SET OF REAR PARKING SENSOR (L200)	Damaged	280.00 FS	*280.00 FS
23	1		*COVER ,RR BUMPER RH	Cut	35.00 FS	*35.00 FS
24	1		*COVER RR BUMPER	Cut	45.00 FS	*45.00 FS
25	1		*REINFORCEMENT RR BUMPER	Bent	703.00 FS	*703.00 FS
26	1		*COVER ,RR BUMPER LH	Cut	35.00 FS	*35.00 FS
27	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*280.00 FS
⊢=Fr	anchise part.	S=SpcNet	π.	Total Parts (S\$)	8,069.00	5,784.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	160.00	160.00
2	CHECK WIRING AND ELECTRICAL	New	100.00	100.00
3	REMOVE REAR CARGO COMPLETE ASSY TO FACILITATE REPAIR WORK	New	640.00	640.00
4	REPAIR REAR END PANEL	New	640.00	640.00
5	PAINT WORK REAR END PANEL & CABIN FLOOR	New	640.00	640.00
6	APPLY BODY SEALANT	New	120.00	120.00
7	APPLY ANTI RUST COATING	New	120.00	120.00
8	CARRY OU FLOOR PULLING	New	640.00	640.00
9	TO REPLACE CARGO DOOR ,REAR BUMPER ,REAR REINFORCEMENT ,REAR LHS FENDER ,REAR END PANEL TO REPAIR ACCIDENT AFFECTED AREA	New	6,400.00	2,560.00
10	PAINT WORK ON CARGO DOOR ,REAR LHS FENDER ,REAR END PANEL	New	2,200.00	1,650.00
11	TO REPLACE REAR PARKING SENSOR	New	180.00	0.00
12	TO R&R REAR CAMERA	New	180.00	120.00
	Gross Labo	ur Cost (S\$)	12,020.00	7,390.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >