

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Altus Facilities Engineering Pte Ltd 9 Dairy Farm Heights #06-22 The Sky Woods Singapore 677670 Billing Address : 124 Pioneer Ro Contact No Mobile: 96670956	Cust No/Name /Altus Facilities Engineering Pt Reg No/Reg Date GBH5524G / 09/07/2018 Date In/Mileage / 0 Chassis No MMCJYKL10HH024999 Engine No 4N15UCA0948 Make/Model MITCV/17MY L200 D/CAB 2.4 AT (T95) Colour/Trim W03 POLAR WHITE SOL/ BK/ BLACK/GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00147	Cash	19/06/2024/ 20:39	TLL	1210/ Lim Teng Keat	50700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
TP CLAIM III								
DOA 25/05/2024								
SUR								
OO REPAIR DAYS								
E PNT88000								6400.00
TO REPLACE CARGO DOOR, REAR BUMPER, REAR REINFORCEMENT,								
REAR LHS FENDER, REAR END PANEL								
TO REPAIR ACCIDENT AFFECTED AREA								
E PNT98000								2200.00
PAINT WORK ON CARGO DOOR, REAR LHS FENDER, REAR END PANEL								
M SUNDRY								180.00
TO REPLACE REAR PARKING SENSOR								
E PNT88000								180.00
TO R&R REAR CAMERA								
M SUNDRY								85.00
TO SUPPLY REAR NUMBER PLATE WITH CASING								
M SUNDRY								50.00
C&C EMBLEM								
M SUNDRY								50.00
SUNDRIES								
M	FACE,RR BUMPER				1.00	1074.00	00.00	1074.00
M	COVER,RR BUMPER				1.00	45.00	00.00	45.00
M	COVER,RR BUMPER,LH				1.00	35.00	00.00	35.00
M	COVER,RR BUMPER,RH				1.00	35.00	00.00	35.00
M	REINFORCEMENT,RR BUMPER				1.00	703.00	00.00	703.00
M	GATE,RR BODY,RR				1.00	1301.00	00.00	1301.00
M	MARK,THREE-DIA				1.00	74.00	00.00	74.00
M	MARK,DIESEL				1.00	31.00	00.00	31.00
M	DECAL,COMMON RAIL				1.00	4.00	00.00	4.00
M	MARK,L200				1.00	31.00	00.00	31.00
M	MARK,MITSUBISHI				1.00	66.00	00.00	66.00
M	SILL,RR BODY FLOOR RR END				1.00	439.00	00.00	439.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Altus Facilities Engineering Pte Ltd 9 Dairy Farm Heights #06-22 The Sky Woods Singapore 677670 Billing Address : 124 Pioneer Rd Contact No Mobile: 96670956	Cust No/Name /Altus Facilities Engineering Pt Reg No/Reg Date GBH5524G / 09/07/2018 Date In/Mileage / 0 Chassis No MMCJYKL10HH024999 Engine No 4N15UCA0948 Make/Model MITCV/17MY L200 D/CAB 2.4 AT (T95) Colour/Trim W03 POLAR WHITE SOL/ BK/ BLACK/GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	19/06/2024/ 20:39	TLL	1210/ Lim Teng Keat	50700
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	SILL,RR BODY FRAME	1.00	350.00	00.00	350.00
M	GATE,RR BODY SIDE,LH	1.00	1182.00	00.00	1182.00
M	PNL,R/BODY SIDE SKRT,RR LH	1.00	128.00	00.00	128.00
M	LAMP ASSY,COMB,RR LH	1.00	488.00	00.00	488.00
M	LAMP ASSY,COMB,RR RH	1.00	488.00	00.00	488.00
M	LAMP ASSY,LICENSE PLATE	1.00	32.00	00.00	32.00
Estimate					

Confirm & accepted by

Nett	15,651.00
9% GST on	1408.59
Total Payable	17,059.59

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.