



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24110513/Kqp3e2
50 RAFFLES PLACE #03-03	Date:	11/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGH 6194J	Veh. Inspected	SNJ 3867C
Policy No.	-	Coverage	0
Claim No.	CMTD2403805/THE	Excess	\$0.00
Assign From	THELMA	Assign Date	25/11/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER (A)	C.C	2487
Engine No.	A25A5493156	Year of Reg.	27/01/2021
Chassis No.	JTEAD3BH60J000118	Colour	METALLIC PEARL WHITE
Odometer	101693 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60R18	YOKOHAMA	9
L/H Front Tyre	225/60R18	YOKOHAMA	9
R/H Rear Tyre	225/60R18	YOKOHAMA	9
L/H Rear Tyre	225/60R18	YOKOHAMA	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/11/2024	Inspection Date	26/11/2024
Survey held at	160 SIN MING DRIVE SIN MING AUTOCITY #06-01 SINGAPORE 575722 - REPAIRER: SQM PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days