

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24110514/AMA3Q2**Date:** 17/06/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MPCM000138  
**Claimant Vehicle No :** SLB6349C **Insured Vehicle No :** SJV5552G  
 Date of Loss: 31/10/2024 Nature of Claim: TP Claim No: MPC2024D0014139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB6349C**  
 Make & Model: HONDA FIT, 1.3 G F-Package (A) Engine No: L13B1300821  
 Reg. Date: 15/04/2016 (Man. Year: 2015) Chassis No: GK31200814  
 Colour: Silver Odometer: 46258 km  
 Engine Capacity: 1317 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 6,960.72          | 1,634.56          | 5,326.16          | 76.52         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 3,730.00          | 1,750.00          | 1,980.00          | 53.08         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>10,690.72</b>  | <b>3,384.56</b>   | <b>7,306.16</b>   | <b>68.34</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,700.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 10,690.72         | 2,700.00          | 7,990.72          | 74.74         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 962.16            | 243.00            | 719.16            | 74.74         |
| <b>Nett Amount (S\$)</b>                        | <b>11,652.88</b>  | <b>2,943.00</b>   | <b>8,709.88</b>   | <b>74.74</b>  |
| <b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b> |                   | 360.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.18              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>3,305.18</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>3,300.00</b>   |                   |               |

INSPECTION

Date of Assignment: 19/02/2025  
 Date Inspected: 19/02/2025 Inspected At: Joo Hak Kee Auto Pte Ltd (HQ)  
 Singapore 408701  
 Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |   |
|---------------|--|---|
| Reference     |  |   |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 21 May 2025)                   |
| Parts:        | 144  | HONDA FIT 1.3 G F-Package (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                               |
| Print Code:   | (Unsubmitted, no print-code for SLB6349C)  |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                    | Not Necessary | 620.20 FL   | *- FL      |
| 2   | 2   |          | *FRONT BUMPER RETAINER LH/RH     | Not Necessary | 57.00 FL    | *- FL      |
| 3   | 1   |          | *FRONT LH HEADLAMP               | Not Necessary | 1,250.70 FL | *- FL      |
| 4   | 1   |          | *FRONT LH HEADLAMP BRACKET       | Not Necessary | 129.80 FL   | *- FL      |
| 5   | 1   |          | *FRONT LH FENDER                 | Not Necessary | 580.90 FL   | *- FL      |
| 6   | 1   |          | *FRONT LH FENDER INNER SHIELD    | Not Necessary | 257.90 FL   | *- FL      |
| 7   | 1   |          | *FRONT DOOR LH                   | Repair        | 560.80 FL   | *- FL      |
| 8   | 1   |          | *REAR BUMPER                     | Deformed      | 692.70 FL   | *545.00 FL |
| 9   | 2   |          | *REAR BUMPER RETAINER LH/RH      | Not Necessary | 57.00 FL    | *- FL      |
| 10  | 1   |          | *REAR LH FENDER                  | Repair        | 697.20 FL   | *- FL      |
| 11  | 1   |          | *REAR FENDER INNER SHIELD LH     | Not Necessary | 191.00 FL   | *- FL      |
| 12  | 1   |          | *REAR FENDER INNER AIR DUCT LH   | Not Necessary | 38.90 FL    | *- FL      |
| 13  | 1   |          | *REAR DOOR LH                    | Dented        | 620.90 FL   | *620.90 FL |
| 14  | 1   |          | *ROCKER PANEL LH                 | Dented        | 489.80 FL   | *489.80 FL |
| 15  | 1   |          | *REAR WHEEL BEARING AND HUN LH   | Not Necessary | 340.70 FL   | *- FL      |
| 16  | 1   |          | *REAR AXLE                       | Not Necessary | 1,052.90 FL | *- FL      |
| 17  | 1   |          | *FRONT BUMPER CLIPS              | Not Necessary | 80.00 FS    | *- FS      |
| 18  | 1   |          | *REAR BUMPER CLIPS               | Necessary     | 80.00 FS    | *30.00 FS  |
| 19  | 1   |          | *FRONT FENDER INNER SHIELD CLIPS | Not Necessary | 80.00 FS    | *- FS      |
| 20  | 1   |          | *REAR FENDER INNER SHIELD CLIPS  | Not Necessary | 80.00 FS    | *- FS      |
| 21  | 1   |          | *REAR RIM LH                     | Cut           | 280.00 FS   | *280.00 FS |
| 22  | 1   |          | *REAR TYRE LH                    | Not Necessary | 250.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |          |          |
|---|----------|----------|
| Sub Total (\$\$)                                    | 8,488.40 | 1,965.70 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,527.68 | 331.14   |
| Total Parts (\$\$)                                  | 6,960.72 | 1,634.56 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO RESPRAY PAINTING ON THE CHARGE BODY PARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT   | New      | 1,500.00        | 800.00          |
| 2                               | TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RESTRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT | New      | 1,500.00        | 800.00          |
| 3                               | REMOVE REINSTALL AND REPLACE FRONT AND REAR DOOR INNER MECHANISM TO ASSIST REPAIR   | New      | 150.00          | 60.00           |
| 4                               | REMOVE REINSTALL AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR  | New      | 250.00          | 0.00            |
| 5                               | TO REMOVE REINSTALL ELECTRICAL WIRING HARNESS   | New      | 150.00          | 30.00           |
| 6                               | APPLY RUST COATING CHEMICAL ON AFFECTED AND CONSISTENT AREAS AND PANELS   | New      | 180.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>3,730.00</b> | <b>1,750.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >