

和 好 贸 易

# HUA HO TRADING

新加坡 德福工業區 C 德福十巷大牌 6 號 門牌 # 01-540  
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,  
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FZ6789K

Items	Price
Exhaust Pipe Protector / CUT	\$89
Right side Front Panel / CUT	\$105
Front Mug guard / CUT	\$98
Right Side Signal Light / CUT	\$75
Right Side Lever X	\$60
Outer Panel (lower R) / CUT	\$198
Lower Panel (lower R black) / CUT	\$95
Radiator Panel / CUT	\$55
Labour Charge	\$150 1/2
Total	\$925

Steve (LKK)

26/11/24, 11.30 am

m n

P/P

by 01 shg

2 days



HUA HO TRADING

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: