

和 好 貿 易

HUA HO TRADING

新加坡 德福工業區 C 德福十巷大牌 6 號門牌 # 01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FZ6789K

Items	Price
Exhaust Pipe Protector / CUT	\$89 /
Right side Front Panel / CUT	\$105 /
Front Mug guard / CUT	\$98 /
Right Side Signal Light / CUT	\$75 /
Right Side Lever X nn	\$60
Outer Panel (lower R) / CUT	\$198 /
Lower Panel (lower R black) / CUT	\$95 /
Radiator Panel / CUT	\$55 /
Labour Charge	\$150 1/2
Total	\$925

Steve (LKK)

26/11/24, 11.30 am

m n

P/P

by 01 shg

2 days

715

-10%

643.50 + 120 (Labour) = 763.50 (P/P)



HUA HO TRADING

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: