1/17/25, 1:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110518/KMA3Q2

Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01

Claimant Vehicle WD6313P Insured Vehicle No: SLF6455H

No:

Date of Loss: 21/11/2024 Nature of Claim: TP Claim No: MFL2024D0013894

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WD6313P

CAMC HN5311X40D9M6, 11.8 D (M) Make & Model: Engine No: CM6D2840060122A00083 Reg. Date: 29/12/2022 (Man. Year: 2022) Chassis No: LZ5N2DE5XNB005151

Colour: Multi-colour Odometer: 61928 km

Engine Capacity: 11813 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D/D) Front Left Side: Rear Left Side: HILO 6/6/8/8 mm Roadone 4/5 mm Front Right Side: Roadone 4/5 mm Rear Right Side: HILO 6/6/8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,472.60	2,720.70	5,751.90	67.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,070.00	1,170.00	52.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,712.60	3,790.70	6,921.90	64.61
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	10,712.60	3,000.00	7,712.60	72.00
+ Loss of Use (3.0 x S\$	150.00/day) (S\$)	450.00		
+ Doc/	Search Fee (S\$)	27.25		
N	ett Liability (S\$)	3,477.25		
Global Sum	Settlement (S\$)	3,450.00		

INSPECTION

Date of Assignment: 26/11/2024

> TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING

Date Inspected: 26/11/2024 Inspected At: **AUTOCITY**

Singapore 575722

Estimated Period of Repair: 3.0 days

KENNETH KONG Manager: Daphne Lee Mooi Ngiuk Adjuster:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Jan 2025)

Parts: N/A CAMC HN5311X40D9M6 11.8 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WD6313P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,985.00 FL	*- FL
2	1		*HEADLAMP LH	Mtg Cracked	1,485.00 FL	*875.00 FL
3	1		*SIGNAL LAMP LH	Mtg Cracked	859.00 FL	*381.20 FL
4	1		*FRONT BUMPER OUTER NET/COVER	Bent	580.00 FL	*580.00 FL
5	1		*STEP PANEL HOUSING LH	Cracked	850.00 FL	*516.80 FL
6	1		*STEP PANEL TOP LH	Repair	335.00 FL	*- FL
7	1		*STEP PANEL CENTER LH	Bent	335.00 FL	*335.00 FL
8	1		*STEP PANEL BOTTOM LH	Distorted	335.00 FL	*335.00 FL
9 E=Ers	1	part. L=ListIte	*STEP PANEL LOWER SUPPORT	Repair	1,650.00 FL	*- FL
1 -1 16	111011130	part. L-Listite	mbisc.	Sub Total (S\$)	9,414.00	3,023.00
			- List Item Discount o	n L Items 10.00/10.00% (S\$)	941.40	302.30
				Total Parts (S\$)	8,472.60	2,720.70
			Report was unsubmitted o	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	LABOUR CHARGES	New	1,000.00	500.00			
2	TO DO ANTI RUST	New	120.00	0.00			
3	TO CHECK WIRING SYSTEM	New	120.00	20.00			
4	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,000.00	550.00			
	Gro	oss Labour Cost (S\$)	2,240.00	1,070.00			
Report was unsubmitted during this print-out.							

< END OF ESTIMATES >