

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24110520/KQP3M4**Date:** 05/12/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SH2264A **Insured Vehicle No :** SJY7453E

Date of Loss: 22/11/2024 Nature of Claim: TP Claim No: DMPC2401621H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH2264A**

Make & Model: TOYOTA COROLLA AXIO, 1.5 X (A) Engine No: 2NR8684669

Reg. Date: 09/06/2017 (Man. Year: 2016) Chassis No: NRE1610022545

Colour: Yellow/Black Odometer: 243453 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm

Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,556.56	3,587.50	969.06	21.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,630.00	1,880.00	53.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,066.56</b>	<b>5,217.50</b>	<b>2,849.06</b>	<b>35.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,066.56</b>	<b>4,100.00</b>	<b>3,966.56</b>	<b>49.17</b>

INSPECTION

Date of Assignment: 25/11/2024

Date Inspected: 26/11/2024 Inspected At: CHOON HOCK MOTOR TRADING CO  
BLK 176 SIN MING DRIVE  
#05-05 SIN MING AUTOCARE  
SINGAPORE 575721

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH2264A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	850.20 FL	*850.20 FL
2	1		*REAR BOOT INNER GARNISH	Distorted	229.20 FL	*229.20 FL
3	2		*REAR BOOT HINGES	Repair	273.60 FL	*- FL
4	1		*REAR LOCK	Dented	94.30 FL	*94.30 FL
5	1		*REAR BOOT OUTER HOLDER	Warped	300.80 FL	*300.80 FL
6	1		*REAR BOOT LOGO	Necessary	50.30 FL	*50.30 FL
7	2		*REAR LAMP	Cracked	1,198.40 FL	*1,198.40 FL
8	1		*REAR LAMP INNER PANEL	O/S Bent	267.60 FL	*133.80 FL
9	1		*REAR BUMPER	Bent	530.50 FL	*530.50 FL
10	2		*REAR BUMPER SIDE RETAINER	Distorted	184.60 FL	*184.60 FL
11	1		*REAR PANEL	Bent	602.20 FL	*602.20 FL
12	1		*REAR PANEL GARNISH	Dented	218.90 FL	*218.90 FL
13	1		*REAR EXHAUST PIPE	Repair	372.30 FL	*- FL
14	2		*REAR EXHAUST PIPE RUBBER	Serviceable	62.60 FL	*- FL
15	1		*REAR BOOT RUBBER (50%) (SN)	Distorted/Dented	185.20 FN	*92.60 F
16	1		*REAR SENSOR	Dented	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	5,640.70	4,685.80
- List Item Discount on L Items 20.00/25.00% (S\$)	1,047.10	1,098.30
- Nett Item Discount on N Items 20.00/0.00% (S\$)	37.04	0.00
Total Parts (S\$)	4,556.56	3,587.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	180.00	100.00
2	REMOVE AND REFIT SENSOR	New	100.00	50.00
3	REMOVE AND REFIT EXHAUST PIPE	New	180.00	0.00
4	WIRING	New	100.00	20.00
5	PANEL BEATING	New	1,300.00	600.00
6	SPRAY PAINTING	New	1,500.00	800.00
7	RUSTPROOF	New	150.00	60.00
Gross Labour Cost (\$\$)			3,510.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >