

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110521/AVP3M4**Date:** 18/03/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002221981
Claimant Vehicle No :	SKS4109P	Insured Vehicle No :	FBR5682E
Date of Loss:	24/11/2024	Nature of Claim:	TP
		Claim No:	381881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS4109P	Engine No:	L15Z12100057
Make & Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Chassis No:	MRHDD4870FP000048
Reg. Date:	14/04/2015 (Man. Year: 2015)	Odometer:	222184 km
Colour:	Orange		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,809.99	2,121.10	2,688.89	55.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,630.00	1,470.00	47.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,909.99	3,751.10	4,158.89	52.58
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,909.99	3,000.00	4,909.99	62.07

INSPECTION

Date of Assignment:	26/11/2024	
Date Inspected:	26/11/2024	Inspected At:
Estimated Period of Repair:	4.0 days	

HUA MENG SPRAY PAINTING WORKSHOP
1 KAKI BUKIT AVE 6
#01-61 AUTOBAY
SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2025)
Parts:	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS4109P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	111.78 FL	*111.78 FL
2	1		*REAR TAILGATE	Dented	1,256.14 FL	*993.00 FL
3	2		*REAR TAILGATE HINGE	Not Necessary	88.54 FL	*- FL
4	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	456.78 FL	*- FL
5	1		*REAR TAILGATE UPPER LOCK	Damaged	254.49 FL	*254.49 FL
6	1		*REAR TAILGATE LOWER CATCH	Not Necessary	254.49 FL	*- FL
7	1		*REAR TAILGATE INNER BOARD	Not Necessary	212.98 FL	*- FL
8	1		*REAR TAILGATE WEATHER STRIP	Cut	111.20 FL	*111.20 FL
9	1		*REAR TAILGATE MOBILIO EMBLEM	Necessary	40.48 FL	*40.48 FL
10	1		*REAR TAILGATE RS EMBLEM	Necessary	40.02 FL	*40.02 FL
11	1		*REAR TAILGATE IVTEC EMBLEM	Necessary	33.00 FL	*33.00 FL
12	1		*REAR END PANEL	Repair	361.90 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Deformed	104.42 FL	*104.42 FL
14	1		*REAR BUMPER	Deformed	533.37 FL	*533.37 FL
15	2		*REAR BUMPER SIDE HOLDER	Not Necessary	90.84 FL	*- FL
16	1		*REAR BUMPER LOWER MOULDING	Cut	262.54 FL	*262.54 FL
17	1		*REAR BUMPER REFLECTOR	O/S Cut	74.74 FL	*37.37 FL
18	2		*REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FL	*- FL
19	1		*REAR EXHAUST PIPE	Not Necessary	857.67 FL	*- FL
20	1		*REAR EXHAUST PIPE CHROME	Not Necessary	107.41 FL	*- FL
21	1		*REAR BUMPER RH INNER SPONG1	Damaged	67.20 FL	*67.20 FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
23	1		*REAR END PANEL INNER SEALANT	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,949.99	2,638.87
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,140.00	517.77
Total Parts (\$\$)	4,809.99	2,121.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE + REINSTALL REAR WINDSCREEN	New	150.00	120.00
2	REMOVE + REINSTALL REVERSE SENSOR	New	150.00	50.00
3	REMOVE + REINSTALL EXHAUST PIPE	New	150.00	80.00
4	REMOVE + REINSTALL BOOTLID INNER GARNISH	New	150.00	80.00
5	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT	New	1,300.00	700.00
6	RESPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,100.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >