3/3/25, 11:27 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG24110523/EVP3M4

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 03/03/2025

REFERENCE

Insured/Claimant: LEONG YEW MENG Policy No: 7230024167

Date of Loss: 24/11/2024 Nature of Claim: OD Claim No: 8176940405SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ69Z

Make & Model: AUDI E-TRON, GT (MATRIX 21") (A) Engine No: HIDDEN

Reg. Date: 11/04/2022 (Man. Year: 2022) Chassis No: WAUZZZFW2N7006777

Colour: Yellow Odometer: 28043 km

Engine Capacity: 0 cc

Market Value/New Car

Price: S\$430,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 ZR21 Rear Tyre Size: 265/35 ZR21
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,250.00	4,998.40	7,251.60	59.20
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,852.00	4,552.00	1,300.00	22.21
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	18,102.00	9,550.40	8,551.60	47.24
	- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
	(S\$)	16,102.00	7,550.40	8,551.60	53.11
	+ GST 9.00/9.00% (S\$)	1,449.18	679.54	769.64	53.11
	Nett Amount (S\$)	17,551.18	8,229.94	9,321.24	53.11

INSPECTION

Date of Assignment: 26/11/2024

Date Inspected: PREMIUM AUTOMOBILES PTE LTD (UBI)
55 UBI ROAD 1

SINGAPORE 408699

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

1		*FRONT BUMPER			
1		I KONT BOMFEK	Repair	3,843.00 FS	*- FS
		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	223.00 FS	*-FS
1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
1		*FRONT FENDER - LH	Dented	6,248.00 FS	*4,998.40 FS
1		*FRONT FENDER SUPPORT - LH	Not Necessary	220.00 FS	*- FS
1		*FRONT CONSOLE - LH	Not Necessary	460.00 FS	*-FS
1		*FRONT FENDER SUPPORT - LH	Not Necessary	99.00 FS	*- FS
1		*FRONT FENDER BRACKET - LH	Not Necessary	40.00 FS	*- FS
1		*FRONT FENDER BRACKET - LH	Not Necessary	40.00 FS	*- FS
1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	46.00 FS	*- FS
1		*FRONT WHEEL HOUSING LINER - UPPER	Not Necessary	381.00 FS	*- FS
1		*FRONT WHEEL HOUSING LINER - LOWER	Not Necessary	209.00 FS	*- FS
1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
chise p	oart. S=SpcN	lett.	_		
			Total Parts (S\$)	12,250.00	4,998.40
			-		
1 1 1 1 1 1 1	hise ţ	hise part. S=SpcN	*FRONT FENDER - LH *FRONT CONSOLE - LH *FRONT FENDER SUPPORT - LH *FRONT FENDER BRACKET - LH *FRONT FENDER BRACKET - LH *FRONT FENDER BRACKET - LH REAR *FRONT WHEEL HOUSING LINER - UPPER *FRONT WHEEL HOUSING LINER - LOWER *SUNDRIES hise part. S=SpcNett.	*FRONT FENDER - LH *FRONT FENDER SUPPORT - LH Not Necessary *FRONT CONSOLE - LH Not Necessary *FRONT FENDER SUPPORT - LH Not Necessary *FRONT FENDER BRACKET - LH Not Necessary *FRONT FENDER BRACKET - LH Not Necessary *FRONT FENDER BRACKET - LH REAR Not Necessary *FRONT WHEEL HOUSING LINER - UPPER *FRONT WHEEL HOUSING LINER - LOWER Not Necessary *SUNDRIES Not Necessary *SUNDRIES	*FRONT FENDER - LH *FRONT FENDER SUPPORT - LH *FRONT CONSOLE - LH Not Necessary *FRONT FENDER SUPPORT - LH Not Necessary *FRONT FENDER SUPPORT - LH Not Necessary *FRONT FENDER BRACKET - LH REAR Not Necessary *FRONT WHEEL HOUSING LINER - UPPER *FRONT WHEEL HOUSING LINER - LOWER *SUNDRIES hise part. S=SpcNett. *Total Parts (S\$) 12,250.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS	New	800.00	800.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FENDER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	· New	1,800.00	1,200.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,300.00
5	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
	Gross Labour	5,852.00	4,552.00	
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >