



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLF 9739U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH HEADLAMP	CRACKED	\$1,899.00	\$1,899.00
1	FRONT RH HEADLAMP RETAINER	NOT NECESSARY	\$215.00	\$0.00
1	FRONT RH FENDER	DENTED	\$898.00	\$450.80
1	FRONT RH FENDER GARNISH	DEFORMED/TORN	\$355.00	\$355.00
1	FRONT BUMPER RETAINER	CRACKED	\$142.00	\$65.50
1	FRONT RH DOOR HINGES	NOT NECESSARY	\$110.00	\$0.00
1	FRONT BONNET	DENTED/BENT	\$1,677.00	\$1,099.20
10	FRONT RH FENDER GARNISH CLIPS	NOT NECESSARY	\$80.00	\$0.00
1	FENDER INNER SUPPORT (ADDITIONAL)	TO REPAIR SEE LABOUR	\$455.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,166.20)	(\$773.90)
			\$4,664.80	\$3,095.60

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT RIGHT PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF FENDER INNER SUPPORT }		\$1,000.00	\$300.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT }		\$0.00	\$0.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS		\$0.00	\$0.00
	TO CHECK WIRING		\$180.00	\$50.00
	SPRAY PAINTING FOR REAR PORTIONS AFFECTED PARTS		\$900.00	\$500.00
	PROGRAMMING FOR HYBRID SYSTEM RESET		\$0.00	\$0.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE		\$0.00	\$0.00
	3D WHEEL ALIGNMENT		\$0.00	\$0.00
	TO APPLY WATERPROOFING SEALER ON END AND FRONT SUPPORT PANELS		\$0.00	\$0.00
			\$2,080.00	\$850.00

GRAND TOTAL			\$6,744.80	\$3,945.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,100.00

Report Ref No: CS/INC24110527/Uvh3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

TOTAL FOR SPARE PARTS: \$ 4,664.80 \$ 3,095.60
TOTAL FOR LABOUR : \$ 2,080.00 \$ 850.00
TOTAL REPAIR COST: \$ 6,744.80 \$ 3,945.60

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.