

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SLF9739U
Chassis No. : RU11204710
Engine No. : L15B4404710
Date of Accident : 21.11.2024

Reference No. : 241121-TPC-JSSM05
Make/Model : HONDA / VEZEL
Date : 26.11.2024

Replacement of Damaged Parts

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's Estimates</u>
1	1	Front RH Headlamp	Damaged CM	\$ 1,899.00
2	1	Front RH Headlamp Retainer	Necessary ^ ^	\$ 215.00
3	1	Front RH Fender	Buckled 00	\$ 898.00
4	1	Front RH Fender Garnish	Damaged 2/11/24	\$ 355.00
5	1	Front Bumper Bracket no to m	Necessary cm	\$ 142.00
6	1	Front RH Door Hinges	Distorted ^ ^	\$ 110.00
7	1	Front Bonnet	Buckled 20/21/24	\$ 1,677.00
8	10	Front RH Fender Garnish Clips	Necessary ^ ^	\$ 80.00
				\$ 5,376.00

Total (Parts): \$ 5,376.00
-20% \$ 4,300.80

Labour Charges

9	To fix & dismantle and remove damaged Front Right Portions; affected damaged portion.	\$ 1,000.00
10	To apply anti rust coat and affected areas	\$ -
11	To check wiring	\$ 180.00
12	Welding and cutting of affected panels, including chassis alignment.	\$ -
13	Spray painting for Rear Portions affected parts	\$ 900.00
14	Programming for Hybrid System Reset	\$ -
15	Diagnose ECU system and reset error code.	\$ -
16	3D Wheel Alignment	\$ -
17	To Apply Waterproofing sealer on End and Front Support Panels	\$ -
Total Labour:		\$ 2,080.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 6,380.80

Less 20% \$ 5,104.64

JSSM AUTOSOLUTIONS PTE LTD

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
meas

90096608

L/S #3100/
26/11/24

Take photo after repair

3 days

p-3869.50
202
3095.60
810
3945.6
202
3110

SUPPLEMENTARY PARTS

Vehicle No. : SLF9739U Reference No. : 241121-TPC-JSSM05
Chassis No. : RU11204710 Make/Model : HONDA / VEZEL
Engine No. : L15B4404710 Date : 26.11.2024
Date of Accident : 21.11.2024

Replacement of Damaged Parts

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's Estimates</u>
1	1	Fender Inner Support	Buckled R	\$ 455.00
				\$ 455.00

Total (Parts): \$ 455.00

-20% \$ 364.00

Labour Charges

2	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ -
3	To apply anti rust coat and affected areas	\$ -
4	To check wiring	\$ -
5	Welding and cutting of affected panels, including chassis alignment.	\$ -
6	Spray painting for Rear Right Portions affected parts	\$ -
7	Programming for Hybrid System Reset	\$ -
8	Diagnose ECU system and reset error code.	\$ -
9	3D Wheel Alignment	\$ -
10	To Apply Waterproofing sealer on End and Front Support Panels	\$ -
Total Labour:		\$ -

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 364.00

Less 20% \$ 291.20