

**SUPPLEMENTARY PARTS**

Vehicle No. : SLF9739U  
Chassis No. : RU11204710  
Engine No. : L15B4404710  
Date of Accident : 21.11.2024

Reference No. : 241121-TPC-JSSM05  
Make/Model : HONDA / VEZEL  
Date : 26.11.2024

**Replacement of Damaged Parts**

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's Estimates</u>
1	1	Fender Inner Support	Buckled R	\$ 455.00
				\$ 455.00

Total (Parts): \$ 455.00  
-20% \$ 364.00

**Labour Charges**

2	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ -
3	To apply anti rust coat and affected areas	\$ -
4	To check wiring	\$ -
5	Welding and cutting of affected panels, including chassis alignment.	\$ -
6	Spray painting for Rear Right Portions affected parts	\$ -
7	Programming for Hybrid System Reset	\$ -
8	Diagnose ECU system and reset error code.	\$ -
9	3D Wheel Alignment	\$ -
10	To Apply Waterproofing sealer on End and Front Support Panels	\$ -
Total Labour:		\$ -

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 364.00

Less 20% \$ 291.20