



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNK 3696Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR LH	DENTED/BENT	\$1,450.00	\$1,350.00
1	FRONT DOOR TRIM LH	NOT NECESSARY	\$447.00	\$0.00
2	FRONT DOOR HINGE LH	NOT NECESSARY	\$214.00	\$0.00
1	FRONT DOOR CHROME MOULDING LH	NOT NECESSARY	\$175.00	\$0.00
1	FRONT DOOR LOCK LH	NOT NECESSARY	\$397.00	\$0.00
1	FRONT DOOR HANDLE LH	NOT NECESSARY	\$244.00	\$0.00
1	FRONT DOOR WEATHERSTRIP LH	NOT NECESSARY	\$175.00	\$0.00
1	FRONT DOOR GLASS LH	NOT NECESSARY	\$457.80	\$0.00
1	FRONT DOOR GLASS MOULDING LH	NOT NECESSARY	\$175.60	\$0.00
1	REAR DOOR LH	TO REPAIR SEE LABOUR	\$1,255.00	\$0.00
1	REAR DOOR TRIM LH	NOT NECESSARY	\$447.00	\$0.00
2	REAR DOOR HINGE LH	NOT NECESSARY	\$214.00	\$0.00
1	REAR DOOR CHROME MOULDING LH	NOT NECESSARY	\$175.00	\$0.00
1	REAR DOOR LOCK LH	NOT NECESSARY	\$397.00	\$0.00
1	REAR DOOR HANDLE LH	NOT NECESSARY	\$244.00	\$0.00
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	\$175.00	\$0.00
1	REAR DOOR GLASS LH	NOT NECESSARY	\$457.80	\$0.00
1	REAR DOOR GLASS MOULDING LH	NOT NECESSARY	\$175.60	\$0.00
1	ROCKER PANEL GARNISH LH	CUT/TORN	\$1,257.00	\$780.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	\$1,455.00	\$0.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$988.00	\$0.00
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	\$145.00	\$0.00
1	REAR BUMPER REFLECTOR COVER LH	NOT NECESSARY	\$145.00	\$0.00
	<b>LESS 20.00% DISCOUNT</b>		(\$2,253.16)	(\$426.00)
			\$9,012.64	\$1,704.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RIM LH (SN)	CUT/WARPED	\$700.00	\$350.00
1	REAR DOOR CLIP (SN)	NOT NECESSARY	\$55.00	\$0.00
1	SET REAR FENDER CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$855.00	\$350.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND LIGHTING SYSTEM	NOT NECESSARY	\$150.00	\$20.00
	REMOVE AND REFIT FRT DOOR MECHANISM		\$600.00	\$50.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH		\$150.00	\$0.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LH, REAR FENDER LH AND REAR BUMPER		\$1,200.00	\$300.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,200.00	\$800.00
	APPLY ANTI RUST ON AFFECTED AREAS		\$100.00	\$30.00
			\$3,400.00	\$1,200.00
GRAND TOTAL			\$13,267.64	\$3,254.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,600.00
Report Ref No: CS/AGI24110535/Uqp3m4				

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.